

WILLOWS/GLENN CO (WLW)(KWLW) 1 W UTC-8(-7DT) N39°30.95' W122°13.04'

SAN FRANCISCO

141 B NOTAM FILE RIU

L-2G

RWY 16-34: H4125X100 (ASPH) S-38, D-53 MIRL

IAP

RWY 16: Road. Rgt tfc.

RWY 34: VASI(V4L)—GA 3.0° TCH 31'.

RWY 13-31: H3788X60 (ASPH) S-12

RWY 13: Trees. Rgt tfc.

RWY 31: Thld dsplcd 243'.

SERVICE: FUEL 100LL LGT ACTIVATE MIRL Rwy 16-34 and VASI Rwy 34—CTAF.


AIRPORT REMARKS: Attended 1530-2330Z. Fuel 24 hr card lock.

AIRPORT MANAGER: 530-934-6530

COMMUNICATIONS: CTAF/UNICOM 122.8

® OAKLAND CENTER APP/DEP CON 132.2

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.



WOODLAKE (O42) 2 S UTC-8(-7DT) N36°23.93' W119°06.41'

SAN FRANCISCO

425 B TPA—1225(800) NOTAM FILE RIU

RWY 07-25: H2203X50 (ASPH-TRTD)

RWY 07: Trees.

RWY 25: Bldg.

SERVICE: FUEL 100LL

AIRPORT REMARKS: Unattended. Arpt not approved for ngt use. Gross pavement strength provided by arpt manager, 8000 lbs.

AIRPORT MANAGER: 559-564-8055

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.