

IGIUGIG (IGG)(PAIG) O S UTC-9(-8DT) N59°19.44' W155°54.11'

90 B NOTAM FILE IGG

RWY 05-23: 3000X75 (GRVL-DIRT) MIRL 0.6% up SW

RWY 05: Trees.

RWY 23: Brush.

SERVICE: **FUEL** 100LL **LGT** ACTIVATE MIRL Rwy 05-23, rotating bcn and windcone lghts—CTAF.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Fuel avbl 1800-0200Z±. Ctc 907-720-8716 for pricing and availability after hrs and hol. Rwy soft during spring breakup and after heavy rain. Rwy 05-23 up to 6" deep circular ruts near thld Rwy 23. Soft sfc near Rwy 23 thld. Fuel sales and restroom fac offered.

AIRPORT MANAGER: 907-571-1261

WEATHER DATA SOURCES: AWOS-3P 119.925 (907) 533-3350. (WX CAM)

COMMUNICATIONS: CTAF 122.8

Ⓡ **ANCHORAGE CENTER APP/DEP CON** 118.8

RADIO AIDS TO NAVIGATION: NOTAM FILE AKN.

KING SALMON (H) (H) VORTACW 112.8 AKN Chan 75 N58°43.48' W156°45.14' 020° 44.7 NM to fld. 95/16E.

TACAN antenna offset 150' se

TACAN AZIMUTH unusable:

130°-140° byd 13 NM blo 4,000'

130°-140° byd 30 NM

332°-348° byd 19 NM blo 5,000'

DME unusable:

332°-348° byd 19 NM blo 5,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.

KODIAK

L-2J, 3C

IAP

