

TERRACE BC (CYXT) 3 S UTC-8(-7DT) N54°28.11' W128°34.70'

H-10, L-1D

713 B NOTAM FILE CYXT Not insp.

RWY 15-33: H4797X148 (ASPH) HIRL

RWY 15: ODALS. REIL. PAPI(P2R)—GA 3.5°. RVR

RWY 33: SSALR. REIL. PAPI(P2L)—GA 3.5°. Rgt tfc. RVR

RWY 03-21: H5316X148 (ASPH)

RWY 21: .Thld dsplcd 707'.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 03: TORA-5316 TODA-6300 ASDA-5316 LDA-5316

RWY 15: TORA-7497 TODA-8481 ASDA-7497 LDA-7497

RWY 21: TORA-5316 TODA-6300 ASDA-5316 LDA-4519

RWY 33: TORA-7497 TODA-8481 ASDA-7497 LDA-7497

SERVICE: FUEL 100LL, JET A1, FS-II **LGT** PAPI limitation/restriction. PAPI Rwy 33 to be used only within 2 NM of thld. Hi terrain reduces operational length of Rwy 33 PAPI.

AIRPORT REMARKS: Attended 13-08Z (DT 12-07Z). Gliders opr off rwy to SW of arpt by NOTAM. CAUTION: Displ thld Rwy 21 marked by hi-vis barrels. Ngt ops not recommended unless all hazard bcns are opr. Recommend that only pilots familiar with the lcl area use the arpt during hrs of darkness. Twy A and B AGN IIIB. Twy B unctld first 2000' from apron. Fuel avbl 1230-0400Z (DT1130-0300Z) ctc 250-638-1564, OT call out charge. ARFF services: Participating CAT 5 1745-0325Z (DT 1645-0225Z) for sked pax flt, other acct 2 hr PN 250-615-7636. Call out chg. Designated CAT 6 1330-0740Z (DT1230-0640Z) for scheduled commercial. Tran acct must park in SE corner of Apron. Itinerant parking with tiedowns on grass May to Oct. N side main apron stands 1-3 are rstd to sked tfc only. Itinerant pilot/pax access via pilot access door on E end of tml bldg. No access/egress via tml bldg facility is permitted. Exceptions require prior approval of aprt opr. Corporate itinerant prkg available. Win maint 13-08Z (DT 12-07Z). No win maint Rwy 03-21. Ltd hrs CRFI, PLR/PCN. Rwy 21 slope 0.69% down. All stands PPR.

COMMUNICATIONS:

RADIO 122.0 (E) PTC avbl.

RCO 123.375 (PACIFIC RADIO)

VANCOUVER CENTER APP/DEP CON 128.4 269.1

VFR ADVISORY SVC call Terrace Radio on Mandatory Frequency (MF) 3700 MSL within 5 NM.

RADIO AIDS TO NAVIGATION

NDB(MHW) 332 XT N54°22.44' W128°35.07' 343° 5.7 NM to fld./19E.

KITIMAT NDB(HZ) 203 ZKI N54°03.25' W128°40.21' 348° 25.1 NM to fld./19E.

ILS/DME 110.1 I-XT Chan 38 Rwy 33. Localizer reliable only within 10° either side of centerline.

COMM/NAV/WEATHER REMARKS: Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA). METAR H24. TAF H24, issue times: 01, 07, 13, 19Z.

TESLIN YT (CYZW) 0 NW YUKON GOV'T UTC-8(-7DT) N60°10.37' W132°44.63'

WHITEHORSE

2303 B AOE NOTAM FILE CYZW Not insp.

H-1C

RWY 09-27: 5023X100 (GRVL) HIRL

RWY 09: REIL. PAPI(P2L)—GA 3.0°. Rgt tfc.

RWY 27: REIL. PAPI(P2L)—GA 4.0°.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 09: TORA-5023 TODA-5220 ASDA-5023 LDA-5023

RWY 27: TORA-5023 TODA-5220 ASDA-5023 LDA-5023

SERVICE: LGT ACTIVATE LIRL Rwy 09-27 and rot bcn—122.1. PAPI may require 3-5 min to activate via ARCAL in cold temperatures.

AIRPORT REMARKS: Ltd winter maintenance. Rwy sfc soft in spring and when wet. Fuel storage by permit only ctc opr. Rwy 27 slope down 0.52%. Compacted snow/grvl mix during winter conds. Sfc may be soft during freeze and thaw periods.

COMMUNICATIONS:

RADIO 122.1 (V) (1300-0100Z‡ Jun 1-Sep 30; 1600-0000Z‡ Oct 1-May 31)

COMM/NAV/WEATHER REMARKS: Kamloops 866-WXBRIEF (Toll free within Canada) or 866-541-4101 (Toll free within Canada & USA). CARS: 867-390-2525 ltd hrs. METAR dur CARS hrs OT LWIS. TAF 1800-0000Z‡ Oct 1-May 31; 1500-0100Z‡ Jun 1-Sep 30; issue times: 1800Z‡ Oct 1-May 31; 1500Z‡, 1800Z‡ Jun 1-Sep 30.