

BISHOP INTL (See FLINT on page 185)

BLISSFIELD

BETZ (44G) 2 N UTC-5(-4DT) N41°51.30' W83°52.25'

691 NOTAM FILE LAN

RWY 09-27: 2602X92 (TURF)

RWY 09: Thld dsplcd 415'. Road.

RWY 27: Thld dsplcd 375'. Road.

SERVICE: FUEL 100LL

AIRPORT REMARKS: Unattended. 100LL avbl by prior arrangement; phone amgr. For snow conds durg winter months call amgr.

Rwy 09-27 soft in spring. Rwy 09 -3' ditch 10' from thld. Rwy 09-27 8' seasonal crops in pri sfc may rstr vis to rwy cones. Rwy 09-27 and dsplcd thlds mkd with cones.

AIRPORT MANAGER: 517-499-4860

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Detroit Apch at 734-955-1404.

**DETROIT
COPTER**

BOIS BLANC ISLAND (6Y1) 3 NW UTC-5(-4DT) N45°45.98' W84°30.23'

664 B NOTAM FILE LAN

RWY 10-28: H3498X75 (ASPH) MIRL 0.6% up W

RWY 28: REIL. PAPI(P4L)—GA 4.0° TCH 33'.

SERVICE: LGT Actvt REIL Rwy 28; PAPI 28; MIRL Rwy 10-28—CTAF.
AIRPORT REMARKS: Unattended. For svc call amgr. Deer and birds on and invof arpt. Rwy & twy may not be plowed full wid drg winter; to verify field conditions call amgr.

AIRPORT MANAGER: 812-320-0792

COMMUNICATIONS: CTAF 122.9

® **MINNEAPOLIS CENTER APP/DEP CON** 134.6

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.

RADIO AIDS TO NAVIGATION: NOTAM FILE PLN.


PELLSTON (L) VORTACW 111.8 PLN Chan 55 N45°37.84'
W84°39.85' 046° 10.6 NM to fld. 836/6W.

VOR unusable:

301°-339°

GCP has azm only, no DME at GCP

**LAKE HURON
L-31C
IAP**



BOULDER CANYON (See BELDING on page 160)