

BATES CITY

HARRY S TRUMAN RGNL (2M1) 2 NW UTC-6(-5DT) N39°01.18' W94°05.19'

KANSAS CITY

860 NOTAM FILE COU
RWY 03-21: 4400X70 (GRVL)
RWY 03: Tree.
RWY 21: Trees.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z. After 0000Z all gates are locked. PAEW infov arpt. Migratory birds on and infov arpt during fall and winter. Rwy 03-21 insufficient rwy safety area lengths beyond each rwy end. Rwy 03 end has steep slope with fence, trees, and road. Rwy 21 end has fence, trees and road. Rwy 03-21 width variance 70-80'.

AIRPORT MANAGER: 816-690-8800
COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City Apch at 816-329-2710.

BETHANY MEML (75K) 2 NE UTC-6(-5DT) N40°16.61' W94°00.45'

OMAHA

1035 NOTAM FILE COU
RWY 03-21: H2255X48 (ASPH) LIRL(NSTD) 0.4% up NE
RWY 03: Trees. Rgt tfc.
RWY 21: Thld dspcd 143'. Bldg.

SERVICE: LGT LIRL Rwy 03-21 three clicks to ACTIVATE—CTAF. Rwy 03-21 NSTD LIRL due to incorrect spacing and non-frangible mounts.

AIRPORT REMARKS: Unattended. Rwy 03-21 has multiple open cracks, pavement raveling and producing foreign object damage. Rwy 03 nstd basic markings, rwy centerline incorrect spacing of stripes and gaps at designation marking. Markings faded. Rwy 21 nstd basic markings, rwy centerline incorrect spacing of stripes and gaps at designation markings and incorrect lateral spacing of designation numbers. Rwy 3-21 markings faded. Nstd rwy safety areas byd each rwy end, Rwy 03 incorrect terrain gradients, Rwy 21 large drop off, brush, small trees, fence and road.

AIRPORT MANAGER: 660-425-3511
COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

BISMARCK MEML (H57) 1 SE UTC-6(-5DT) N37°45.53' W90°37.01'

ST LOUIS

1038 B NOTAM FILE STL
RWY 17-35: H2050X50 (ASPH-AFSC) LIRL(NSTD)
RWY 17: Trees.
RWY 35: Tree. Rgt tfc.

SERVICE: LGT Rwy 17-35 NSTD LIRL, 1 thld lgts 3-7' from rwy end on each side of rwy at each thld.

AIRPORT REMARKS: Attended irregularly. Wildlife on and infov arpt.

AIRPORT MANAGER: 573-315-9326

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.

BOLIVAR MUNI (M17) 4 E UTC-6(-5DT) N37°35.77' W93°20.86'

KANSAS CITY

1092 B NOTAM FILE COU
RWY 18-36: H4000X75 (ASPH) S-12.5 MIRL

RWY 18: PAPI(P2L)—GA 3.75° TCH 40'.

RWY 36: PAPI(P2L)—GA 3.0° TCH 40'.

SERVICE: S4 FUEL 100LL, JET A LGT Rwy 18-36 MIRL dusk-0530Z; after 0530Z activate—CTAF. ACTIVATE PAPI Rwy 18 and Rwy 36—CTAF.

AIRPORT REMARKS: Attended Mon-Sat 1400-2300Z. Fuel credit card 100LL and Jet A hrs 24 hrs avbl. Extensive student pilot training infov arpt. Wildlife and birds on and infov arpt.

AIRPORT MANAGER: 417-777-6800

COMMUNICATIONS: CTAF/UNICOM 123.0


Ⓡ **SPRINGFIELD APP/DEP CON** 124.95

CLEARANCE DELIVERY PHONE: For CD ctc Springfield Apch at 417-868-5620/5619.

RADIO AIDS TO NAVIGATION: NOTAM FILE SGF.

SPRINGFIELD (VH) (H) VORTAC 116.9 SGF Chan 116 N37°21.36' W93°20.04' 353° 14.4 NM to fld. 1240/4E.

VOR unusable:
 073°-085° byd 40 NM blo 18,000'
 095°-120° byd 40 NM
 121°-137° byd 40 NM blo 18,000'



L-16F
 IAP

BOLLINGER-CRASS MEML (See VAN BUREN on page 281)