

PORT ISABEL—CAMERON CO (PIL)(KPIL) 10 NW UTC-6(-5DT) N26°09.97' W97°20.75'

BROWNSVILLE

19 B NOTAM FILE PIL

H-7C, L-20H, 21A

RWY 13-31: H8001X200 (ASPH-CONC) S-105, D-135, 2D-230 MIRL

IAP

RWY 13: REIL. PAPI(P2L)—GA 2.0° TCH 27'.

RWY 31: REIL. PAPI(P2L)—GA 3.0° TCH 41'.

RWY 08-26: H5317X150 (CONC) S-50, D-60, 2D-110

RWY 08: Fence.

RWY 26: Trees.

RWY 03-21: H5000X150 (ASPH-CONC) S-30, D-45, 2D-90

RWY 03: Brush.

RWY 21: Tree.

RWY 17-35: H4200X75 (ASPH-CONC) S-30, D-45, 2D-90

RWY 35: Tower.

SERVICE: S2 **FUEL** 100LL, JET A **OX 2** **LGT** Rwy 13 REIL OTS. Rwy 31 REIL OTS.

AIRPORT REMARKS: Attended 1400-2300Z±. Parachute Jumping. 100LL & Jet A avbl self serve & full serv. Rwy 03-21 pavement has heavy grass encroachment. Rwy 08-26 rough pavement. Rwy has heavy grass encroachment. No position holding markings on numerous twys apchng rwy intersections. Loose gravel/pavement at intersection of Rwy 13 and northeast twy connecting Rwy 13 and Rwy 21. Rwy 03-21 and Rwy 08-26 markings faded.

AIRPORT MANAGER: (956) 761-3700

WEATHER DATA SOURCES: ASOS 118.525 (956) 233-1954.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **VALLEY APP/DEP CON** 119.5

CLNC DEL 119.2

CLEARANCE DELIVERY PHONE: For CD etc Corpus Christi Apch at 361-299-4230.

RADIO AIDS TO NAVIGATION: NOTAM FILE BRO.

BROWNSVILLE (H) (H) VORTACW 116.3 BRO Chan 110 N25°55.44' W97°22.52' 357° 14.6 NM to fld. 10/9E.

TACAN AZIMUTH unusable:

360°-290° byd 24 NM

DME unusable:

360°-290° byd 24 NM

VOR unusable:

271°-290° byd 20 NM

320°-335°

360°-270° byd 24 NM