

**IGIUGIG** (IGG)(PAIG) 0 S UTC-9(-8DT) N59°19.44' W155°54.11'

90 B NOTAM FILE IGG

**RWY 05-23:** 3000X75 (GRVL-DIRT) MIRL 0.6% up SW

**RWY 05:** Trees.

**RWY 23:** Brush.

**SERVICE:** FUEL 100LL LGT ACTIVATE MIRL Rwy 05-23, rotating bcn and windcone lgts—CTAF.

**AIRPORT REMARKS:** Unattended. Rwy condition not monitored, recommend visual inspection prior to using. Fuel avbl 1800-0200Z±. Ctc

907-720-8716 for pricing and availability after hrs and hol. Rwy soft during spring breakup and after heavy rain. Rwy 05-23 up to 6" deep circular ruts near thld Rwy 23. Soft sfc near Rwy 23 thld. Fuel sales and restroom fac offered.

**AIRPORT MANAGER:** 907-571-1261

**WEATHER DATA SOURCES:** AWOS-3P 119.925 (907) 533-3350. (WX CAM)

**COMMUNICATIONS:** CTAF 122.8

Ⓡ **ANCHORAGE CENTER APP/DEP CON** 118.8

**RADIO AIDS TO NAVIGATION:** NOTAM FILE AKN.

**KING SALMON (H) (H) VORTACW** 112.8 AKN Chan 75 N58°43.48'

W156°45.14' 020° 44.7 NM to fld. 95/16E.

TACAN antenna offset 150' se

TACAN AZIMUTH unusable:

130°-140° byd 13 NM blo 4,000'

130°-140° byd 30 NM

332°-348° byd 19 NM blo 5,000'

DME unusable:

332°-348° byd 19 NM blo 5,000'

**COMM/NAV/WEATHER REMARKS:** For a toll free call to Kenai FSS dial 1-866-864-1737.

**KODIAK**

L-2J, 3C

IAP

