

BOIS BLANC ISLAND (6Y1) 3 NW UTC-5(-4DT) N45°45.98' W84°30.23'

LAKE HURON

664 B NOTAM FILE LAN

L-31C

RWY 10-28: H3498X75 (ASPH) MIRL 0.6% up W

IAP


RWY 28: REIL, PAPI(P4L)—GA 4.0° TCH 33'.

SERVICE: LGT Actvt REIL Rwy 28; PAPI 28; MIRL Rwy 10-28—CTAF.**AIRPORT REMARKS:** Unattended. For svc call amgr. Deer and birds on and in/ov arpt. Rwy & twy may not be plowed full wid drg winter; to verify field conditions call amgr.**AIRPORT MANAGER:** 812-320-0792**COMMUNICATIONS:** CTAF 122.9Ⓜ **MINNEAPOLIS CENTER APP/DEP CON** 134.6**CLEARANCE DELIVERY PHONE:** For CD ctc Minneapolis ARTCC at 651-463-5588.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PLN.**PELLSTON (L) (L) VORTACW** 111.8 PLN Chan 55 N45°37.84' W84°39.85' 046° 10.6 NM to fld. 836/6W.

VOR unusable:

301°-339°

GCP has AZM only, no DME at GCP

**BOULDER CANYON** (See BELDING on page 159)