**MICHIGAN** 187

## FRANKFNMUTH

WM 'TINY' ZEHNDER FLD (66G) 2 SE UTC-5(-4DT) N43°18.86′ W83°42.60′

DETROIT

639 NOTAM FILE LAN

RWY 09-27: 2500X100 (TURF) 0.3 up F

RWY 09: Thid dsplcd 394'. Road.

AIRPORT REMARKS: Unattended. Deer and Irg birds on and invof arpt. No snow removal-ctc amgr to vfy ficon. Rwy 09-27 soft in spring and aft hvy rain. Rwy 09, -7' ditch 60' fm thld. Rwy 27 +8' seasonal crops, 10' fm thr, 100' left and right of cntrln. Rwy 09-27 and dthr mkd with 3' yellow cones.

AIRPORT MANAGER: 810-614-4826

**COMMUNICATIONS: CTAF** 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490

## **FRANKFORT**

FRANKFORT DOW MEML FLD (FKS)(KFKS) 2 SE UTC-5(-4DT) N44°37.51′ W86°12.05′

633 B NOTAM FILE FKS

GRFFN BAY L-31B IAP

RWY 15-33: H4050X75 (ASPH) S-25 MIRL 0.7% up NW

RWY 15: Thid dsplcd 1094'. Road.

RWY33: REIL. PAPI(P2R)—GA 3.0° TCH 35'. Thid dspicd 111'. Tree. SERVICE: FUEL 100LL LGT Actvt REIL Rwy 33; PAPI Rwy 33; MIRL Rwy 15-33-CTAF (3 mike clicks turns off).


AIRPORT REMARKS: Attended ireg. For on call attendant call amgr. Hang glider activity along Lake Michigan lakeshore. Deer and birds on and invof arpt. 100LL; avbl self svc via credit card. Arpt bcn located on hill 1.25 miles northwest of arpt. Ramp fee for commercial acft. Admin bldg aces: press 5-3-2-1.

AIRPORT MANAGER: 231-352-9118

WEATHER DATA SOURCES: AWOS-3P 118.325 (231) 352-7573. Wind unrel. COMMUNICATIONS: CTAF/UNICOM 123.05

® MINNEAPOLIS CENTER APP/DEP CON 132.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.



SIX MILE HELIPORT (Y59) 7 SE UTC-5(-4DT) N44°32.66′ W86°07.36′ **GREEN BAY** 

755 NOTAM FILE LAN HELIPAD H1: 51X52 (TURF) **HELIPORT REMARKS:** Unattended.

AIRPORT MANAGER: 231-383-2798 **COMMUNICATIONS: CTAF 122.9** 

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.