

CAMBRIDGE MUNI (CDI)(KCDI) 3 S UTC-5(-4DT) N39°58.50' W81°34.66' **CINCINNATI**
 799 B NOTAM FILE CDI **L-29B**
RWY 04-22: H4298X75 (ASPH-GRVD) S-24 MIRL **IAP**
RWY 04: REIL. PAPI(P4L)—GA 4.0° TCH 29'. Thld dsplcd 400'. P-line.
RWY 22: REIL. PAPI(P4R)—GA 3.55° TCH 28'. Road.
SERVICE: FUEL 100LL, JET A+ **LGT** ACTIVATE REIL Rwy 04 & 22; MIRL Rwy 04-22—CTAF. PAPI Rwy 04 & 22 opr
 consly. PAPI Rwy 04 unusbl byd 4° left and 8° right and of cntrln. PAPI Rwy 22 unusbl byd 8° right and 4° left of cntrln.
AIRPORT REMARKS: Attended Mon-Sat 1300-2200Z†. Deer, birds & otr wildlife invof arpt. 100LL self svc. Rwy 04 obstn lgtd
 hills SW of arpt. Ramp fees for coml acft, exc flt trng acft, CDI based acft, ovngt hngr stay, fuel purchase of 25 gallons or
 top off. Tsnt hngr PPR.
AIRPORT MANAGER: 740-517-0458
WEATHER DATA SOURCES: AWOS-3 118.525 (740) 435-0086.
COMMUNICATIONS: CTAF/UNICOM 123.075
 (R) **INDIANAPOLIS CENTER APP/DEP CON** 124.45 (West Side Opns)
 (R) **CLEVELAND CENTER APP/DEP CON** 126.95 (East Side Opns) ctc Cleveland ARTCC at 440-774-0226.
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland ARTCC at 440-774-0226/0490.
RADIO AIDS TO NAVIGATION: NOTAM FILE ZZY.
ZANESVILLE (H) (DH) VORW/DME 114.95 ZZY Chan 96(Y) N39°56.45' W81°53.56' 088° 14.7 NM to fld.
 898/6W.
 DME unusable:
 160°-170° byd 30 NM blo 3,500'
NEWCOMERTOWN (L) DME 111.8 CTW Chan 55 N40°13.75' W81°28.59' 197° 15.9 NM to fld.
 1180. NOTAM FILE CLE.
 DME unusable:
 010°-074° byd 28 NM blo 4,000'
 075°-085° byd 23 NM blo 7,100'
 086°-140° byd 28 NM blo 4,000'

CANTON

STARK CO SHERIFF HELIPORT (5D1) 4 E UTC-5(-4DT) N40°50.41' W81°18.50' **DETROIT**
 1135 NOTAM FILE CLE
HELIPAD H1: H120X75 (ASPH)
HELIPAD H1: Pole.
HELIPORT REMARKS: Attended continuously. Ingress-Egress clkws fm pad. Ingress NE FATO 220°, egress NE FATO 040°. Extsv
 cracking, loose stones. Heli marked with `H`.
AIRPORT MANAGER: 234-804-1440
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at
 440-774-0223.

CARROLL CO-TOLSON (See CARROLLTON on page 266)

CARROLLTON

CARROLL CO-TOLSON (TSO)(KTSO) 1 SE UTC-5(-4DT) N40°33.70' W81°04.69' **DETROIT**
 1164 B TPA-2014(850) NOTAM FILE CLE **L-29B**
RWY 07-25: H4300X75 (ASPH) MIRL **IAP**
RWY 07: REIL. PAPI(P2L). Trees.
RWY 25: REIL. PAPI(P2L). Trees.
SERVICE: S4 FUEL 100LL, JET A **LGT** Actvt REIL Rwy 07 and 25; MIRL Rwy 07-25—CTAF.
AIRPORT REMARKS: Unattended. Deer on and invof arpt. 100LL and Jet A avbl H24 via credit card. Acft maint avbl, call
 330-499-9790. Twy lgts at turn around buttons/rwy entrance.
AIRPORT MANAGER: 330-323-8626
COMMUNICATIONS: CTAF/UNICOM 122.7
 (R) **CLEVELAND APP/DEP CON** 125.5 (1100-0600Z†)
 (R) **CLEVELAND CENTER APP/DEP CON** 120.6 (0600-1100Z†) ctc Cleveland ARTCC at 440-774-0223.
CLEARANCE DELIVERY PHONE: For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at
 440-774-0223.
RADIO AIDS TO NAVIGATION: NOTAM FILE CLE.
NEWCOMERTOWN (L) DME 111.8 CTW Chan 55 N40°13.75' W81°28.59' 042° 27.0 NM to fld. 1180.
 DME unusable:
 010°-074° byd 28 NM blo 4,000'
 075°-085° byd 23 NM blo 7,100'
 086°-140° byd 28 NM blo 4,000'