

NORTON MUNI (NRN)(KNRN) 1 N UTC-6(-5DT) N39°51.03' W99°53.68'

WICHITA

2384 B NOTAM FILE ICT

L-10H

RWY 16-34: H4701X60 (CONC) HIRL 0.5% up NW

IAP

RWY 16: REIL. PAPI(P2L)—GA 3.0° TCH 44'.**RWY 34:** REIL. PAPI(P2L)—GA 3.0° TCH 43'.**RWY 08-26:** 2117X125 (TURF)**RWY 08:** Tree.**SERVICE:** FUEL 100LL, JET A LGT HIRL Rwy 16-34 opr constly.

ACTVT PAPI Rwy 16 and 34—CTAF.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z†. For svc after hrs call 785-877-2201/3447. Fuel: self-service avbl 24 hrs a day. Rwy 08-26 sfc rough.**AIRPORT MANAGER:** 785-877-2201**WEATHER DATA SOURCES:** AWOS-3PT 118.275 (785) 874-4277.**COMMUNICATIONS:** CTAF 122.9① **DENVER CENTER APP/DEP CON** 132.7**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HLC.**HILL CITY (VH) (H) VORTACW** 113.7 HLC Chan 84 N39°15.52'


W100°13.55' 015° 38.7 NM to fld. 2690/8E.

VOR unusable:

271°-274° byd 40 NM

279°-289° byd 40 NM blo 4,800'

279°-289° byd 47 NM

**NORWICH** (49K) 1 E UTC-6(-5DT) N37°27.33' W97°50.02'

WICHITA

1494 NOTAM FILE ICT

RWY 17-35: 3230X80 (TURF) LIRL(NSTD)**RWY 17:** P-line.**RWY 35:** Thld dsplcd 180'. Railroad.**SERVICE:** LGT NSTD LIRL Rwy 17-35, incorrect spacing.**AIRPORT REMARKS:** Unattended. Rwy 35 dsplcd thld marked with 2 lgts either side with painted tires. Irrigation pump and fuel tank 75' left of centerline Rwy 17 150' S of thld.**AIRPORT MANAGER:** 620-704-3339**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Wichita Apch at 316-350-1520.**OAKLEY MUNI** (OEL)(KOEL) 2 SE UTC-6(-5DT) N39°06.71' W100°49.01'

WICHITA

3045 B NOTAM FILE ICT

H-5B, L-10G

RWY 16-34: H5000X75 (CONC) S-30 MIRL 0.5% up NW

IAP

RWY 16: REIL. PAPI(P2L)—GA 3.0° TCH 44'. Bldg.**RWY 34:** REIL. PAPI(P2L)—GA 3.0° TCH 44'. Tree.**RWY 08-26:** 2153X110 (TURF)**RWY 26:** Road.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 16:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000**RWY 34:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000**SERVICE:** S4 FUEL 100LL, JET A LGT PAPI Rwy 16-34—CTAF.

Dusk-0430Z†. MIRL Rwy 16-34 preset low instst Dusk-0430Z†; to incr instst—CTAF; after 0430Z† ACTVT MIRL Rwy 16-34—CTAF. PAPI Rwy 16-34—CTAF. Rwy 16 PAPI unusable beyond 8° right and 6° left of centerline. Rwy 34 PAPI unusable beyond 8° left of centerline.

AIRPORT REMARKS: Attended Mon-Fri 1400-2300Z†. For service after hrs call 785-672-0147. Self svc fuel avbl 24 hrs with credit card.**AIRPORT MANAGER:** 785-672-0147**WEATHER DATA SOURCES:** AWOS-3 118.325 (785) 671-4194.**COMMUNICATIONS:** CTAF/UNICOM 122.8① **DENVER CENTER APP/DEP CON** 132.7**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.**RADIO AIDS TO NAVIGATION:** NOTAM FILE HLC.**HILL CITY (VH) (H) VORTACW** 113.7 HLC Chan 84 N39°15.52' W100°13.55' 244° 28.9 NM to fld. 2690/8E.

VOR unusable:

271°-274° byd 40 NM

279°-289° byd 40 NM blo 4,800'

279°-289° byd 47 NM

