


BOARDMAN (M50) 4 SW UTC-8(-7DT) N45°48.89' W119°49.23'
 396 B NOTAM FILE MMV
RWY 04-22: H4200X100 (ASPH) S-30 MIRL 0.7% up SW

SEATTLE
 L-13A

RWY 22: Rgt tfc.
SERVICE: LGT ACTIVATE MIRL Rwy 04-22-122.9.
AIRPORT REMARKS: Unattended. Telephone avbl. Twy edge marked with blue reflectors. Rwy 04-22 cntrln in poor cond due to fading.
AIRPORT MANAGER: 541-481-7678
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.
RADIO AIDS TO NAVIGATION: NOTAM FILE PDT.



PENDLETON (VH) (H) VORTACW 114.7 PDT Chan 94 N45°41.91'
 W118°56.32' 267° 37.7 NM to fld. 1575/14E.
 VOR unusable:
 057°-066° byd 40 NM
 067°-078° byd 40 NM blo 29,000'
 096°-106° byd 40 NM blo 8,300'
 096°-106° byd 48 NM blo 18,000'
 107°-117° byd 40 NM
 118°-128° byd 40 NM blo 12,000'
 118°-128° byd 75 NM
 129°-207° byd 40 NM

BROOKINGS (BOK)(KBOK) 1 NE UTC-8(-7DT) N42°04.44' W124°17.39'
 462 B NOTAM FILE BOK

KLAMATH FALLS
 IAP

RWY 12-30: H2901X60 (ASPH) S-11 MIRL 0.9% up NW
RWY 12: PAPI(P2L)—GA 4.0° TCH 40'. Trees. Rgt tfc.
RWY 30: PAPI(P2L)—GA 3.0° TCH 45'. Trees.
SERVICE: FUEL 100LL, JET A LGT ACTIVATE MIRL Rwy 12-30 and PAPI Rwy 12 and Rwy 30—CTAF.
AIRPORT REMARKS: Unattended. Deer and elk invof arpt gnds. Arpt rot bcn lgt beam obscured by taller trees northeast-southeast quadrant.
AIRPORT MANAGER: (541) 254-4278
WEATHER DATA SOURCES: AWOS-3PT 132.025 (541) 412-8682.
COMMUNICATIONS: CTAF/UNICOM 122.8
SEATTLE CENTER APP/DEP CON 124.85
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.