

DILLEY AIRPARK (24R) 2 NW UTC-6(-5DT) N28°41.13' W99°11.35'

SAN ANTONIO
L-20G

542 B NOTAM FILE SJT

RWY 12-30: H3400X60 (ASPH) S-12.5 LIRL 0.4% up SE

RWY 12: Trees.

RWY 30: Sign.

SERVICE: LGT Arpt lgts opr dusk-0500Z†. Rotating bcn OTS indefly. Rwy 12-30 LIRL OTS indefly.

AIRPORT REMARKS: Unattended.

AIRPORT MANAGER: 830-965-1624

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.


RADIO AIDS TO NAVIGATION: NOTAM FILE COT.

COTULLA (VL) (H) VORTACW 115.8 COT Chan 105 N28°27.72'

W99°07.11' 335° 13.9 NM to fld. 522/9E.

VOR unusable:

008°-032° byd 40 NM



DIMITT CO (See CARRIZO SPRINGS on page 273)

DIMITT MUNI (T55) 2 N UTC-6(-5DT) N34°34.00' W102°19.36'

ALBUQUERQUE
H-6G, L-6H

3883 B NOTAM FILE FTW

RWY 01-19: H5500X60 (ASPH) S-15 MIRL

RWY 01: Tree.

RWY 19: Road. Rgt tfc.

SERVICE: FUEL 100LL LGT Actvt MIRL Rwy 01-19—CTAF.

AIRPORT REMARKS: Unattended. For fuel call 806-647-2550 during business hrs. Rwy 01-19 Pavement spalling, cracks with vegetation growing through, loose stones and paint on sfc. Rwy 01 and 19 Markings peeling off pavement.

AIRPORT MANAGER: 806-647-2155

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

TEXICO (VH) (H) VORTACW 112.2 TXO Chan 59 N34°29.71'

W102°50.38' 069° 26.0 NM to fld. 4060/11E.

VOR unusable:

095°-100° byd 40 NM

120°-130° byd 40 NM

210°-272° byd 60 NM blo 10,000'

273°-283° byd 40 NM blo 6,000'

273°-283° byd 46 NM blo 7,000'

273°-283° byd 59 NM

284°-319° byd 40 NM

320°-035° byd 40 NM

TACAN AZIMUTH unusable:

222°-232°

