266 ALASKA

## YAKUTAT

ALSEK RIVER (A57) 44 SE UTC-9(-8DT) N59°11.95′ W138°26.75′

53 NOTAM FILE INU.

RWY 07-25: 1860X12 (TURF)

RWY 07. Tree

RWY 25. Tree

AIRPORT REMARKS: Unattended. Wildlife invof rwy. Erratic winds off mountain range east of rwy. Rwy uneven on both sides with several dips over 12". Maintain centerline ctl during ldg and tkf. Gully on thld Rwy 07, recommend touch down in front of USFS cabin. Rwy 07-25 soft and wet during Spring and after heavy rains. Rwy 07-25 NSTD markings, thld marked with yellow plastic pipes.

AIRPORT MANAGER: 907-784-3359 COMMUNICATIONS: CTAF 122.9

RADIO AIDS TO NAVIGATION: NOTAM FILE YAK.

YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65′ W139°38.89′ 096° 41.4 NM to fld. 41/20E.


VOR unusable:

124°-261° byd 22 NM blo 10,000′

DME unusable:

124°-261° bvd 22 NM blo 10.000′

COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial



DRY BAY (3AK) 44 SE UTC-9(-8DT) N59°09.86′ W138°29.33′ 33 NOTAM FILE JNU

IUNFAU

IIINFΔII

I-1B

RWY 05-23: 3600X170 (GRVL)

RWY 05: Trees

RWY 23: Trees.

AIRPORT REMARKS: Unattended. Rwy condition not monitored, recommend visual inspection prior to Idg. Wildlife may be present on the rwy. Southwest end of rwy beyond thid has soft sand. Windsock 0.2 miles north on the riverbank at the processing plant. Commercial ops may require a commercial use authorization (ctc Glacier Bay National Park 907-697-2230). Helicopter ops are prohibited without a permit from the Glacier Bay National Park superintendent.

AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122.9

COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236.

**EAST ALSEK RIVER** (AK76) 49 SE UTC-9(-8DT) N59°07.58′ W138°24.53′

JUNEAU

39 NOTAM FILE YAK

RWY 02-20: 1500X10 (TURF) 0.3% up N

RWY 02: Trees RWY 20: Trees

AIRPORT REMARKS: Unattended. Turf rwy soft and wet in spring and after heavy rains. Rwy safety area ground rises and falls over 12", maintain centerline control. Rwy used by bears and ATV. Cabin at airstrip maintained by US Forest Svc. Width of path cut through trees 80'. Windsock in fair condition, mounted on spruce tree and partially obscured by other trees.

AIRPORT MANAGER: 907-784-3295 COMMUNICATIONS: CTAF 122 9

RADIO AIDS TO NAVIGATION: NOTAM FILE YAK

YAKUTAT (H) (H) VORW/DME 113.3 YAK Chan 80 N59°30.65′ W139°38.89′ 101° 44.6 NM to fld. 41/20E.

VOR unusable-

124°-261° byd 22 NM blo 10,000′

DMF unusable:

124°-261° byd 22 NM blo 10,000′

COMM/NAV/WEATHER REMARKS: For a toll free call to Juneau FSS dial 1-866-297-2236

ଫଫଫ 133 0000 000 C C C 1000 C 0000000 3333 150+ G G G 0 0 0 0 0 G G G G 00000 0000000 000000 GGG GG 000000 COCO 000000 0 000 000 0 000 000 0 000 000 QQQ Q Q Q 00000 00000 ζ3 `