

**MINNEAPOLIS CITY CO** (45K) 2 SW UTC-6(-5DT) N39°05.66' W97°43.26'

WICHITA

1246 NOTAM FILE ICT

L-101

**RWY 16-34:** H3970X20 (ASPH)**RWY 16:** Trees.**RWY 34:** Trees.**AIRPORT REMARKS:** Attended Apr-Nov dawn-dusk. Arpt opr daylight hrs only.

Deer on and invof arpt.

**AIRPORT MANAGER:** 785-392-3300**COMMUNICATIONS:** CTAF 122.9® **KANSAS CITY CENTER APP/DEP CON** 134.9**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at

913-254-8508.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE SLN.**SALINA (VH) (H) VORTACW** 117.1 SLN Chan 118 N38°55.51'

W97°37.28' 328° 11.2 NM to fld. 1316/7E.


VOR unusable:

017°-026° byd 40 NM

315°-016° byd 15 NM blo 6,000'

DME unusable:

300°-042° byd 15 NM blo 6,000'

**MOLINE****ELK CO** (2K6) 3 NE UTC-6(-5DT) N37°22.86' W96°16.27'

KANSAS CITY

1063 NOTAM FILE ICT

**RWY 18-36:** H2510X40 (ASPH) 0.4% up N**RWY 36:** Pole.**AIRPORT REMARKS:** Unattended. Wildlife on and invof arpt. Rwy 18-36 has centerline marking only. Rwy 36 the poles that constitute the controlling obstruction on the right are not visibly marked or lgtd.**AIRPORT MANAGER:** 620-374-3597**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.**MONTEZUMA MUNI** (K17) 2 SW UTC-6(-5DT) N37°35.14' W100°28.21'

WICHITA

2780 NOTAM FILE ICT

L-15C

**RWY 17-35:** H4000X60 (ASPH) MIRL**RWY 17:** Thld dsplcd 700'. Road.**RWY 35:** Road.**SERVICE:** LGT ACTIVATE MIRL Rwy 17-35—CTAF.**AIRPORT REMARKS:** Unattended. +6 ft irrigation engine/pump located on Rwy 17-35 W edge near windsock.**AIRPORT MANAGER:** 620-846-0550**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Kansas City ARTCC at 913-254-8508.**MORITZ MEML** (See BELOIT on page 88)