KANSAS

COLONEL JAMES JABARA (AAO)(KAAO) 9 NE UTC-6(-5DT) N37°44.85′ W97°13.27′

1421 B NOTAM FILE AAO

WICHITA

RWY18-36: H6101X100 (CONC-GRVD) S-40, D-62 PCN 15 R/B/X/T

H-5C, L-10I, 15D IAP

147

MIRL 0.3% up S

RWY 18: MALSR. PAPI(P4L)-GA 3.0° TCH 45'. Rgt tfc.

RWY 36: REIL. PAPI(P4L)—GA 3.0° TCH 45'.

SERVICE: S4 FUEL 100LL, JET A LGT ACTIVATE MIRL Rwv 18-36. MALSR Rwy 18, REIL Rwy 36-CTAF. PAPI Rwy 18 and Rwy 36 opr cont. FUEL For 24 hr fuel contact FBO.

NOISE: Noise sensitive areas S. SW. and W.

AIRPORT REMARKS: Attended continuously. Migratory birds on and in venty of arpt, all quads. Rwy 18 nstd tfc pat. All tfc pats W of fld. Rwy 36 dsgnd calm wind rwy. PPR for acft carrying Class 1—Division 1.1, 1.2 or 1.3 explosives as defined by 49 CFR 173.50 or as amended. Use ctn for McConnell AFB 9 miles S and Beech Factory arpt 3 miles S. Beech Factory Arpt Class D asp begins 1 mile S Rwy 18. VFR arr and dep recommended to rmn at or blw 2,500 MSL within 5 miles due to heavy mil tfc 3,000 'MSL. Due to 20 'rwy end elev differential, pilots may lose line of sight of otr acft on opposing rwy ends. Acft engine runs above idle not approved on acft prkg ramps.

AIRPORT MANAGER: 316-946-4700

WEATHER DATA SOURCES: ASOS 134.025 (316) 636-2541.

COMMUNICATIONS: CTAF/UNICOM 122.7

® WICHITA APP/DEP CON 134.8 WICHITA CLNC DEL 125.0

AIRSPACE: CLASS E

RADIO AIDS TO NAVIGATION: NOTAM FILE ICT

WICHITA (H) (H) VORTACW 113.8 ICT Chan 85 N37°44.72′ W97°35.03′ 082° 17.3 NM to fld. 1472/7E.

TACAN AZIMUTH unusable: 025°-035° blo 4,000 040°-055° bvd 20 NM 147°-159° blo 4,900° VOR unusable:

025°-035° blo 4 000 ° 147°-159° blo 4,400

ILS/DME 109.55 I-AAO Chan 32(Y) Rwy 18. Class IT.

WICHITA

WESTPORT (71K) 3 SW UTC-6(-5DT) N37°38.86′ W97°23.02′ 1290 NOTAM FILE ICT

RWY 17-35: H2520X30 (ASPH) S-3

RWY 17: Thid dsplcd 400'. Pole.

RWY 35: Fence. Rgt tfc.

SERVICE: S4 FUEL 100LL

AIRPORT REMARKS: Attended dalgt hours. Departures ctc Wichita twr on the ground on frequency 125.7 for departure instructions. If unable—ctc twr on frequency 118.2 upon departure and remain east of the fld until communications are established. Rwy 17-35 has grass encroaching on rwy sides numerous surface cracks.

AIRPORT MANAGER: 316-943-5510 COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Wichita Apch at 316-350-1520.

WESTPORT AUXILIARY (72K) 5 SW UTC-6(-5DT) N37°36.25′ W97°21.53′ WICHITA

1272 NOTAM FILE ICT

RWY 17-35: 2550X50 (TURF)

RWY 17: P-line.

RWY 35: Trees

AIRPORT REMARKS: Unattended. If conditions favorable, balloon traffic in area. Road crosses north end Rwy 17–35; 775 ft from AER 17 large ridge at crossing. Crops both sides of Rwy 17-35. Edge drop off along east edge Rwy 17-35. Rwy 17-35 surface rough and bumpy. 10 ft dirt rd crosses rwy 780 ft fm N end.

AIRPORT MANAGER: 316-943-5510

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Wichita Apch at 316-350-1520.

NC. 17 APR 2025 to 12 JUN 2025

€3 €3 a €3 €3 43 5101 36