
NORTH DAKOTA



TOMLINSON FLD (See NEW ROCKFORD on page 356)

TWIN CITIES TOWNER MUNI (D61) 1 NE UTC-6(-5DT) N48°21.57' W100°23.73' 1484 B NOTAM FILE GFK RWY 03-21: 2810X120 (TURF) 0.3% up NE RWY 03. Road RWY 16-34: 2732X150 (TURF) LIRL RWY 16. Road RWY 34 Road SERVICE: LGT Dusk-Dawn. ACTVT LIRL Rwy 16-34-CTAF. AIRPORT REMARKS: Unattended. Confirm winter conditions after snowstorm with arpt manager 701-537-5137 or 701-537-3519. Rwy 03 has 140' water tower 2000' from thId 600' left of extended centerline. 3' ditch southeast end Rwy 16-34 and southwest end Rwy 03-21. Rwy 03-21 has 5 ft rwy vis sight clnc violation. Rwy 03-21 mkd 3 ft wooden red mkrs on ends and intxn. Rwy 16-34 mkd 3 ft wooden red mkrs on ends and intxn. AIRPORT MANAGER: 701-537-3519 COMMUNICATIONS: CTAF/UNICOM 122.8 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588. ٠ . ٠ ٠ HELIPAD H1: H30X30 (CONC) TRULSON FLD (See PLAZA on page 359) TWIN CITIFS TURTLE LAKE MUNI (91N) 1 SW UTC-6(-5DT) N47°30.58' W100°55.00' 1916 NOTAM FILE GFK RWY 08-26: 3148X120 (TURF) LIRL 0.5% up E SERVICE: LGT ACTIVATE LIRL Rwy 08-26-CTAF. AIRPORT REMARKS: Unattended. Confirm winter conditions with arpt manager before use due to irregular snow removal, call 701-220-0707. Deer and wildlife on and in vicinity of arpt. Rwy 08-26 sfc grass soft when wet. Rwy 08 has 10' dropoff 50' out from thid. Rwy 08-26 during dalgt marked with yellow tires around lgts. AIRPORT MANAGER: (701) 516-3826 COMMUNICATIONS: CTAF/UNICOM 122.8 CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.