

MALONE-DUFORT (MAL)(KMAL) 2 W UTC-5(-4DT) N44°51.22' W74°19.74'

MONTREAL

790 B NOTAM FILE BTV

L-32G

RWY 05-23: H3994X100 (ASPH) S-20 MIRL 0.4% up SW

RWY 05: REIL. PAPI(P2L)—GA 3.15° TCH 42'. Trees.

RWY 23: REIL. PAPI(P2L)—GA 3.0° TCH 43'. Trees.

RWY 14-32: H3250X75 (ASPH) S-12.5 MIRL 0.9% up SE

RWY 14: Trees.

RWY 32: Thld displcd 348'. Tree.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 05: TORA-3994 TODA-3994 ASDA-3994 LDA-3994

RWY 14: TORA-3250 TODA-3250 ASDA-3250 LDA-3250

RWY 23: TORA-3994 TODA-3994 ASDA-3994 LDA-3994

RWY 32: TORA-3250 TODA-3250 ASDA-3250 LDA-2902

SERVICE: FUEL 100LL LGT ACTIVATE PAPI Rwy 05 and Rwy 23, MIRL

Rwy 05-23, Rwy 14-32 and twy lgts—CTAF.

AIRPORT REMARKS: Airport not attended. Rwy 14-32 has snow removal but visual inspection and NOTAM check must be done as town roads are plowed before arpt. Haying activity and equipment present Jun-Sept.

AIRPORT MANAGER: (518) 483-4740

WEATHER DATA SOURCES: AWOS-AV 122.8 (518) 651-2601.


COMMUNICATIONS: CTAF/UNICOM 122.8

® **BOSTON CENTER APP/DEP CON** 135.25

CLEARANCE DELIVERY PHONE: For CD cto Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE MSS.

MASSENA (H) TACAN Chan 88 MSS (114.1) N44°54.87' W74°43.36' 116° 17.2 NM to fld. 198/14W.



MARCY FLD (See KEENE on page 214)