PENNSYLVANIA

CRESCO ROCKY HILL (48P) 1 SE UTC-5(-4DT) N41°08.91' W75°16.52' 1240 NOTAM FILE IPT RWY 09-27: 1000X100 (TURF) RWY 29: Thid dspicd 30'. Trees. RWY 27: Thid dspicd 80'. Trees. AIRPORT REMARKS: Unattended. Deer and wildlife on and invof arpt. Announce tfc on—CTAF 122.9. AIRPORT MANAGER: 570-595-2269 COMMUNICATIONS: CTAF 122.9 CLEARANCE DELIVERY PHONE: For CD ctc Allentown Apch at 800-728-6322.	NEW YORK
 DANVILLE (8N8) 3 SW UTC-5(-4DT) N40°56.90' W76°38.64' 559 B NOTAM FILE IPT RWY 09-27: H3000X60 (ASPH) MIRL 0.4% up E RWY 09: Trees. RWY 27: Trees. SERVICE: S4 LGT Lighting NSTD. ACTVT MIRL Rwy 09-27 drg periods of darkness only—CTAF. Rwy 27 th1d Igts dsplcd 365' from rwy end for ngt displacement. Rwy end Igtd with two red Igts on left side (NSTD). AIRPORT REMARKS: Attended irregularly. After hrs ctc 570-274-6190. Deer and wildlife on and invof arpt. Radio controlled airplane ops N of rwy. Main ramp no prop wash invof main hangar due to acft painting. AIRPORT MANAGER: 570-274-6190 COMMUNICATIONS: CTAF/UNICOM 122.8 WILKES-BARRE APP/DEP CON 126.3 CLEARANCE DELIVERY PHONE: For CD ctc Wilkes-Barre Apch at 570-655-2084. RADIO AIDS TO NAUGATION: NOTAM FILE IPT. MILTON (L) (L) VORTACW 109.2 MIP Chan 29 N41°01.40' W76°39.92' 177° 4.6 NM to fid. 1000/9W. 	NEW YORK L-30J IAP Residential Area &

DECK (See MYERSTOWN on page 294)

DONEGAL SPRINGS AIRPARK (See MOUNT JOY/MARIETTA on page 292)

DOVER

 LAZY B RANCH (ØP8) 3 E UTC-5(-4DT) N40°01.47' W76°48.92'
 NEW YORK

 476
 NOTAM FILE IPT

 RWY 05-23: H2400X60 (ASPH-CONC)
 LIRL 1.3% up SW

 RWY 23: Trees.
 SERVICE: S4

 SERVICE: S4
 LGT For LIRL Rwy 05-23 key 122.9 five times.

 AIRPORT REMARKS: Unattended. Ctc arpt manager 717-292-7029. Deer invof arpt. Rwy 05-23 large patches of conc on edges of rwy with sfc cracking and vegetation growth. Turf area parallel to Rwy 05-23, for taxi only, marked with yellow cones.

 AIRPORT MANAGER: 717-577-8827
 COMMUNICATIONS: CTAF 122.9

 CLEARANCE DELIVERY PHONE: For CD ctc Harrisburg Apch at 800-932-0712.