
DARRINGTON MUNI (1S2) 0 N UTC-8(-7DT) N48°15.52' W121°36.61'

SEATTLE

553 B NOTAM FILE SEA

RWY 10-28: H2491X40 (ASPH) MIRL**RWY 10:** Trees.**RWY 28:** Road.**SERVICE:** LGT ACTVT MIRL Rwy 10-28—CTAF. Arpt bcn OTS.**AIRPORT REMARKS:** Unattended. CLOSED when snow on rwy. Turbulence on hot days ldg west in trns east apch. Twys marked with blue reflectors. Twys rough pavement with swales and depressions.**AIRPORT MANAGER:** 360-631-1928**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

DAVENPORT (68S) 1 W UTC-8(-7DT) N47°39.12' W118°10.43'

SEATTLE

2424 B NOTAM FILE SEA

RWY 06-24: H3260X60 (ASPH) MIRL 0.3% up NE**RWY 24:** Rgt t/c.**SERVICE:** FUEL 100LL**AIRPORT REMARKS:** Attended on call. Mon-Fri 8:00 am to 5:00 pm, call office number, 509-725-4352. After hours call 509-721-0069. Fuel 24 hr credit card svc avbl. Pilots bring own ropes.**AIRPORT MANAGER:** 509-725-4352**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Spokane Apch at 509-742-2522**RADIO AIDS TO NAVIGATION:** NOTAM FILE GEG.**SPOKANE (VH) (H) VORTACW** 115.5 GEG Chan 102 N47°33.90' W117°37.61' 269° 22.8 NM to fld. 2756/14E.

VOR unusable:

007°-022° byd 26 NM blo 7,000'

029°-041° byd 40 NM

307°-337° byd 30 NM blo 9,000'

342°-007° byd 18 NM blo 7,000'

342°-007° byd 25 NM

DE VERE FLD (See CLE ELUM on page 229)
