
SWANSON FLD (See EATONVILLE on page 234)

TACOMA NARROWS (TIW)(KTIW) 4 W UTC-8(-7DT) N47°16.08' W122°34.69'

295 B TPA-1295(1000) LRA NOTAM FILE TIW MON Airport


RWY 17-35: H5002X100 (ASPH-GRVD) S-50, D-80, 2S-102, 2D-80,
2D/2D2-150 MIRL
RWY 17: MALSR. PAPI(P4R)—GA 3.0° TCH 52'.**RWY 35:** REIL. PAPI(P4L)—GA 3.0° TCH 45'. Rgt tfc.
SERVICE: S4 **FUEL** 100LL, JET A **OX 4** **LGT** When ATCT clsd, ACTVT
MALSR Rwy 17; REIL Rwy 35; PAPI Rwy 17 and 35; MIRL Rwy
17-35—CTAF. Rwy 35 PAPI unusbl byd 5.0 degrees left of cntrln.
NOISE: Noise Abatement proc in efct - amgr.**AIRPORT REMARKS:** Attended 1500-0000Z†. Deer on and invof arpt.

Customs - 253-593-6338 ext #2.

AIRPORT MANAGER: 253-798-8550**WEATHER DATA SOURCES:** ASOS (253) 858-6507 LAWRS.**COMMUNICATIONS:** CTAF 118.5 **ATIS** 124.05 **UNICOM** 122.95Ⓡ **SEATTLE APP/DEP CON** 120.1**TOWER** 118.5 (1600-0400Z†) **GND CON** 121.8**CLEARANCE DELIVERY PHONE:** For CD when ATCT is clsd ctc Seattle Apch at
206-214-4723.**AIRSPACE:** CLASS D svc 1600-0400Z†; other times CLASS E.**RADIO AIDS TO NAVIGATION:** NOTAM FILE TCM.**MCCHORD (T) TACAN** Chan 33 TCM (109.6) N47°08.86'

W122°28.50' 315° 8.4 NM to fld. 283/15E.

No NOTAM MP 0800-2300Z† Wed

ILS 109.1 I-TIW Rwy 17. Class IA. Unmonitored when ATCT clsd.**COMM/NAV/WEATHER REMARKS:** Emerg freq 121.5 not mnt at ATCT. LAWRS ops durg ATCT hrs.

SEATTLE

H-1B, L-1D

IAP, AD

TATOOSH N48°17.99' W124°37.62' NOTAM FILE SEA.
(VH) (H) **VORTACW** 112.2 **TOU** Chan 59 151° 22.0 NM to Quillayute. 1650/22E.

VOR unusable:

020°-025° byd 40 NM

085°-090° byd 40 NM

091°-101° byd 40 NM blo 15,000'

091°-101° byd 58 NM

103°-109° byd 40 NM

356°-360° byd 40 NM

RCO 122.5 (SEATTLE RADIO)

SEATTLE

H-1B, L-1D

TEKOA

WILLARD FLD (73S) 2 NE UTC-8(-7DT) N47°14.13' W117°02.62'

2520 B NOTAM FILE SEA

RWY 04-22: H2261X40 (ASPH) MIRL**RWY 04:** Thld dspcd 190'. Trees.**RWY 22:** Thld dspcd 240'.**SERVICE:** S4 **FUEL** 100LL **LGT** ACTIVATE MIRL Rwy 04-22-122.8.**AIRPORT REMARKS:** Unattended. Self svc fuel with credit card. Parachute Jumping. Grass areas not avbl for acft ops.**AIRPORT MANAGER:** 509-322-8643**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Seattle ARTCC at 253-351-3694.

SEATTLE

TIETON STATE (See RIMROCK on page 271)