

FLOYDADA MUNI (41F) 1 N UTC-6(-5DT) N34°00.09' W101°19.82'**DALLAS-FT WORTH**

3187 B NOTAM FILE FTW

L-6H

RWY 17-35: H4600X60 (ASPH) S-15 MIRL

IAP

RWY 17: PAPI(P2L)—GA 3.0° TCH 40'.

RWY 35: PAPI(P2L)—GA 3.0° TCH 39'. Bldg. Rgt t/c.


SERVICE: FUEL 100LL, JET A LGT Dusk-Dawn. MIRL Rwy 17-35 preset to low intst; to incr intst or actvt—CTAF.**AIRPORT REMARKS:** Attended Mon-Sat 1400-0000Z†. Extsv aerial ag ops.**AIRPORT MANAGER:** 806-983-2314**COMMUNICATIONS:** CTAF/UNICOM 122.8

® LUBBOCK APP/DEP CON 119.2 119.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584.**RADIO AIDS TO NAVIGATION:** NOTAM FILE PVW.

PLAINVIEW (VL) (L) VORW/DME 112.9 PVW Chan 76 N34°05.17'

W101°47.41' 091° 23.5 NM to fld. 3400/11E.

**FLUFY** N31°13.13' W94°49.51' NOTAM FILE LFK.**HOUSTON**

NDB (LOMW) 350 LF 075° 4.0 NM to Angelina Co. 205/2E. NDB unmonitored.

FLYIN TIGER (See ANGLETON on page 252)**FLYING C** (See SANGER on page 425)**FLYING H RANCH** (See WHITESBORO on page 450)**FLYING V RANCH** (See LOUISE on page 372)**FOLLETT/LIPSCOMB CO** (T93) 1 E UTC-6(-5DT) N36°26.45' W100°07.43'**WICHITA**

2601 NOTAM FILE FTW

L-15C

RWY 17-35: H4073X60 (ASPH) S-18 1.7% up S

RWY 17: P-line.

RWY 35: Hill.

AIRPORT REMARKS: Unattended. No line of sight btn rwy ends. Rwy 17-35 13 ft wide strip of pavement along west edge of rwy failed, will not support listed wheel weight. Rwy 17-35 extensive pavement cracking with vegetation growing through. Loose stones on rwy. Rwy 17 and Rwy 35 no pavement mrkgs.**AIRPORT MANAGER:** 806-653-2601**COMMUNICATIONS:** CTAF 122.9

® KANSAS CITY CENTER APP/DEP CON 126.95

CLEARANCE DELIVERY PHONE: For CD ctc Kansas City ARTCC at 913-254-8508.**RADIO AIDS TO NAVIGATION:** NOTAM FILE GAG.

MITBEE (VH) (H) VORTACW 115.6 MMB Chan 103 N36°20.62'

W99°52.81' 286° 13.2 NM to fld. 2426/10E.

