

CONTINUED FROM PRECEDING PAGE

AIRSPACE: CLASS D svc Fri–Mon 1200–0600Z†, Tue–Thur 1100–0600Z†, clsd New Years day, Thanksgiving, and Christmas; other times CLASS G.

RADIO AIDS TO NAVIGATION: NOTAM FILE FCS.

(T) (T) VORW/DME 108.8 FCS Chan 25 N38°40.84′ W104°45.42′ at fld. 5822/12E. VOR unmonitored when twr clsd. DME unmonitored.

VOR unusable:

050°–100° blo 15,000′

105°–115° byd 21 NM blo 9,500′

230°–305° byd 10 NM blo 15,000′

DME unusable:

050°–100° blo 15,000′

230°–305° byd 10 NM blo 15,000′

IRONHORSE NDB (MHW) 335 IHS N38°40.71′ W104°45.19′ at fld. 5818/8E. NOTAM FILE DEN. NDB unmonitored when twr clsd. SHUTDOWN.

NDB unusable:

210°–300° byd 20 NM blo 20,000′

ILS/DME 111.75 I–FCS Chan 54(Y) Rwy 31.

CALHAN (5V4) 1 N UTC–7(–6DT) N39°02.90′ W104°17.58′

DENVER

6450 TPA—7250(800) NOTAM FILE DEN

Rwy 17–35: 4565X50 (TURF–GRVL) LIRL(NSTD)

Rwy 17: TRCV(TRIL). Road.

Rwy 35: Trees. Rgt tfc.

SERVICE: S2 LGT Rwy 17–35 NSTD LIRL, north 3000′ rwy lgtd. ACTIVATE NSTD LIRL Rwy 17–35 and VASI Rwy 17 CTAF.

AIRPORT REMARKS: Attended irregularly. Vehicles crossing rwy. Rwy 17–35 width varies from 50′ to 100′. Rwy 17 first 1250′ 45′ wide artificial turf. Be alert, intensive USAF student training invof Colorado Springs and Pueblo Colorado. Aerobatic practice area 1/2 mile west of Rwy 17–35 300′ AGL to 10,000′ MSL. South end rwy has side slope. –6′ ditch 40′ west of centerline. Ground raises on east side of rwy. Rwy 17 has 25′ P–pole 400′ from thld, 110′ R of centerline. Rwy 17–35 has +15′ road 110′ from and parallel to rwy centerline W side of rwy full length. Rwy 35 has +4′ fence 200′ from thld obstruction, aprx +20′ trees 70′ west of centerline for first 500′ of rwy, approx +25′ P–line 850′ from thld obstruction, aprx 2′ burm at rwy thld. See Special Notices—USAF 306 FTG Flight Training Areas, Vicinity of Colorado Springs and Pueblo Colorado.

AIRPORT MANAGER: 719-338-2149

COMMUNICATIONS: CTAF/UNICOM 122.725

CLEARANCE DELIVERY PHONE: For CD ctc Colorado Springs Apch at 719-556-9105.