MICHIGAN 183

FRANKENMUTH

WM 'TINY' ZEHNDER FLD (66G) 2 SE UTC-5(-4DT) N43°18.86′ W83°42.60′

DETROIT

639 NOTAM FILE LAN

RWY 09-27: 2500X100 (TURF) 0.3 up E

RWY 09: Thid dsplcd 394'. Road.

AIRPORT REMARKS: Unattended. Deer and Irg birds on and invof arpt. No snow removal—ctc amgr to vfy ficon. Rwy 09–27 soft in spring and aft hvy rain. Rwy 09, –7′ ditch 60′ fm thld. Rwy 27 +8′ seasonal crops, 10′ fm thr, 100′ left and right of cntrln. Rwy 09–27 and dthr mkd with 3′ yellow cones.

AIRPORT MANAGER: 810-614-4826

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Great Lakes Apch at 269-459-3345, when Apch clsd ctc Cleveland ARTCC at 440-774-0224/0490.

FRANKFORT

FRANKFORT DOW MEML FLD (FKS)(KFKS) 2 SE UTC-5(-4DT) N44°37.51′ W86°12.05′

633 B NOTAM FILE FKS

GREEN BAY L-31B IAP

RWY 15–33: H4050X75 (ASPH) S–25 MIRL 0.7% up NW RWY 15: Thid dsplcd 1094′. Road.

RWY33: REIL. PAPI(P2R)—GA 3.0° TCH 35'. Thid dsplcd 111'. Tree.
SERVICE: FUEL 100LL LGT Actvt REIL Rwy 33; PAPI Rwy 33; MIRL

SERVICE: FUEL 100LL LGT Actvt REIL Rwy 33; PAPI Rwy 33; M Rwy 15–33—CTAF (3 mike clicks turns off).


AIRPORT REMARKS: Attended ireg. For on call attendant call amgr. Hang glider activity along Lake Michigan lakeshore. Deer and birds on and invof arpt. 100LL: avbl self svc via credit card. Arpt bcn located on hill 1.25 miles northwest of arpt. Ramp fee dtrmd bt wt. Admin bldg aces: press 5–3–2–1.

AIRPORT MANAGER: 231-352-9118

WEATHER DATA SOURCES: AWOS-3P 118.325 (231) 352-7573. Wind unrel. COMMUNICATIONS: CTAF/UNICOM 123.05

®MINNEAPOLIS CENTER APP/DEP CON 132.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.



SIX MILE HELIPORT (Y59) 7 SE UTC-5(-4DT) N44°32.66′ W86°07.36′

GREEN BAY

755 NOTAM FILE LAN
HELIPAD H1: 51X52 (TURF)
HELIPORT REMARKS: Unattended.

AIRPORT MANAGER: 231-383-2798
COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Minneapolis ARTCC at 651-463-5588.