

RAVENNA**PORTAGE CO** (POV)(KPOV) 3 N UTC-5(-4DT) N41°12.61' W81°15.10'**DETROIT**

1198 B NOTAM FILE POV

L-30G**RWY 09-27:** H3499X75 (ASPH) MIRL**IAP****RWY 09:** REIL.**RWY 27:** REIL. PAPI(P4L)—GA 3.0° TCH 43'.**SERVICE:** S4 FUEL 100LL, JET A+ OX 3, 4 LGT Actvt REIL Rwy 09 & 27; PAPI Rwy 27; MIRL Rwy 09-27—CTAF.**AIRPORT REMARKS:** Attended Mon-Fri 1300-2100Z†. Unatndd all major hols. Ficon NOTAMs unavbl aft hrs, wkends, and major hols. Deer on & invof arpt. 100LL avbl H24 self svc. Paraglider ops by permit only. Rwy 09-27 all areas off rwy sfc soft when wet or thawing.**AIRPORT MANAGER:** 330-842-6367**WEATHER DATA SOURCES:** AWOS-3 118.675 (330) 298-9353.**COMMUNICATIONS:** CTAF/UNICOM 123.05® **CLEVELAND APP/DEP CON** 125.5 (1100-0600Z†)® **CLEVELAND CENTER APP/DEP CON** 120.6 (0600-1100Z†) ctc Cleveland ARTCC at 440-774-0223.**CLNC DEL** 125.65**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apch at 216-352-2323, when Apch clsd ctc Cleveland ARTCC at 440-774-0223/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CAK.**AKRON (L) (L) VORW/DME** 114.4 ACO Chan 91 N41°06.47' W81°12.09' 344° 6.5 NM to fld. 1197/4W.**DME unusable:**

Byd 10 NM

RED STEWART AIRFIELD (See WAYNESVILLE on page 319)**RICHARD DOWNING** (See COSHOCTON on page 272)**RICKENBACKER INTL** (See COLUMBUS on page 271)**ROSEWOOD** N40°17.27' W84°02.59' NOTAM FILE DAY.**DETROIT**(H) (H) **VORTACW** 117.5 ROD Chan 122 245° 5.6 NM to Sidney Muni. 1080/5W.**H-10G, L-27E****TACAN AZIMUTH** unusable:

000°-120°

125°-135°

VOR unusable:

125°-135°

ROSS CO (See CHILLICOTHE on page 263)**RUHES** (See LEIPSIC on page 288)**ST CLAIRSVILLE****ALDERMAN** (2P7) 3 SW UTC-5(-4DT) N40°03.41' W80°57.79'**DETROIT**

1187 B NOTAM FILE CLE

L-29B**RWY 01-19:** H2840X50 (ASPH) LIRL(NSTD) 0.9% up N**IAP****RWY 01:** Trees.**RWY 19:** Trees.**SERVICE:** LGT ACTVT NSTD LIRL Rwy 01-19—123.3 or call amgr. ACTVT abn—123.3 or call amgr. Rwy 01-19 nstd LIRL due to 15 ft fm edge of pavement.**AIRPORT REMARKS:** Attended 1300Z†-dusk. Ocnl deer, birds and otr wildlife on and invof arpt. Rwy 01-19 surface is weathered with some raveling, med block cracking throughout. South half of ramp poor cond due to broken pavement. Rwy 01-19 nstd basic due to nrs and sml cntrln with nstd spacing. Ldg fee.**AIRPORT MANAGER:** 740-695-0908**COMMUNICATIONS:** CTAF 122.9® **CLEVELAND CENTER APP/DEP CON** 126.95**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland ARTCC at 440-774-0226/0490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE CLE.**BELLAIRE (H) (H) VORW/DME** 117.1 AIR Chan 118 N40°01.02' W80°49.03' 297° 7.1 NM to fld. 1307/7W.