
EAST HADDAM**GOODSPEED** (42B) 1 SE UTC-5(-4DT) N41°26.74' W72°27.34'**NEW YORK**

9 NOTAM FILE BDR

RWY 14-32: H2120X50 (ASPH) S-8 LIRL**RWY 32:** Trees.**SERVICE:** S4 LGT Arpt lgts opr 24 hrs.**AIRPORT REMARKS:** Unattended. Caution deer, birds and waterfowl on and in/ov arpt. Parl turf twy mkd with yellow cones. May be soft when wet or aft rain. Seaplane dock and ramp. Overnight parking fee. Ldg fee.**AIRPORT MANAGER:** (860) 615-9068**COMMUNICATIONS:** CTAF/UNICOM 122.8**CLEARANCE DELIVERY PHONE:** For CD ctc New York Apch at 516-683-2449.

.

WATERWAY 16W-34W: 4500X1000 (WATER)**WATERWAY 16W:** Bridge.**WATERWAY 34W:** Hill.

ELLINGTON (7B9) 2 N UTC-5(-4DT) N41°55.53' W72°27.43'**NEW YORK**

253 NOTAM FILE BDR

RWY 01-19: H1800X50 (ASPH) S-9 RWY LGTS(NSTD)**RWY 01:** Trees.**RWY 19:** Trees.**SERVICE:** S4 FUEL 100LL LGT Non-std LIRL opr dusk-0500Z†, for lgts aft 0500Z† call 860-871-2054 durg bus hrs. Rwy 01-19 non-std LIRL due to spacing, thr lgts outboard of rwy.**AIRPORT REMARKS:** Attended 1300-2300Z†. Parachute Jumping. Extensive helicopter training ops. Acft tfc pat on E side of arpt only. Hel tfc pat on W side of arpt only. Twy pavement failed, extsv cracking, patches, loose aggregate and sml stones. Rwy 01 mkg faded. Rwy 19 mkg faded.**AIRPORT MANAGER:** 860-614-1854**COMMUNICATIONS:** CTAF/UNICOM 123.0**CLEARANCE DELIVERY PHONE:** For CD ctc Yankee Apch at 860-386-3597.

FARMINGTON CT71 N41°42.54' W72°48.13'/363**NEW YORK**

AWOS-AV 129.825 AWOS-AV wx bcst on 129.825 (3 mic clicks).

L-33C, 34I

GOODSPEED (See EAST HADDAM on page 35)
