

OROVILLE

DOROTHY SCOTT INTL (ØS7) 2 NE UTC-8(-7DT) N48°57.54' W119°24.72'

1069 B AOE NOTAM FILE SEA

RWY 15-33: H4017X50 (ASPH) S-5 MIRL

RWY 15: Bldg. Rgt ttc.

RWY 33: Trees.

SERVICE: S4 **FUEL** 100LL **LGT** ACTVT MIRL Rwy 15-33—CTAF.

AIRPORT REMARKS: Attended dawn-dusk. On call for service, alternate number 509-322-2887. Wildlife adj to rwy and twy. Rwy 15-33 cracks in twy pavement. Rwy 15 markings faded. Rwy 33 markings faded. Arpt rotg bcn lctd 1500' east of cntrln of arpt on top of hill aprx 900' above arpt elev. Cstms telephone 509-476-2955. Flight Notification Service (ADCUS) avbl.

AIRPORT MANAGER: 509-476-2345

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE MWH.

MOSES LAKE (VH) (DH) VORW/DME 115.0 MWH Chan 97

N47°12.65' W119°19.01' 340° 105.0 NM to fld.

1193/18E.

VOR unusable:

025°-040° byd 40 NM

055°-070° byd 40 NM

071°-081° byd 40 NM blo 28,000'

175°-198° byd 40 NM blo 6,000'

175°-198° byd 67 NM blo 10,000'

175°-198° byd 70 NM


200°-210° byd 40 NM

220°-230° byd 40 NM

240°-253° byd 40 NM blo 18,000'

254°-260° byd 40 NM

315°-345° byd 40 NM



SCOTT SPB (1WA) 2 N UTC-8(-7DT) N48°58.33' W119°26.36'

915 NOTAM FILE Not insp.

WATERWAY 15W-33W: 10000X500 (WATER)

WATERWAY 33W: Rgt ttc.

AIRPORT MANAGER: 509-476-2926

COMMUNICATIONS: CTAF 122.9

SEATTLE
L-13A

SEATTLE