

REPUBLIC

FERRY CO (R49) 6 NE UTC-8(-7DT) N48°43.09' W118°39.39'

2522 B TPA—3322(800) NOTAM FILE SEA

RWY 17-35: H3498X60 (ASPH) MIRL

RWY 17: Trees. Rgt tfc.

RWY 35: PAPI(P2L)—GA 4.0° TCH 40'. Trees.

SERVICE: LGT ACTVT PAPI Rwy 35; MIRL Rwy 17-35—122.8.

AIRPORT REMARKS: Unattended. Suggest ngt lds be made on Rwy 35.

Rwy 17-35 trees located on unlgtd unmarked mountainous terrain.
P-lines NE of Rwy 17 lgtd dusk-dawn. Wildlife invof of rwy. Rwy 17
and Rwy 35 rwy mrkgs faded.

AIRPORT MANAGER: 616 822-0483

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc: Seattle ARTCC at 253-351-3694.

RADIO AIDS TO NAVIGATION: NOTAM FILE EPH.

EPHRATA (VH) (H) VORTACW 112.6 EPH Chan 73 N47°22.68'
W119°25.44' 360° 86.2 NM to fld. 1250/21E.

VOR unusable:

010°-014° byd 40 NM

042°-054° byd 40 NM

214°-228° byd 40 NM blo 7,000'

214°-228° byd 52 NM blo 10,000'

214°-228° byd 77 NM

229°-247° byd 40 NM

310°-350° byd 25 NM blo 6,500'

310°-353° byd 40 NM

358°-004° byd 40 NM

TACAN AZIMUTH unusable:

280°-295° byd 25 NM blo 7,000'

310°-350° byd 25 NM blo 6,500'

DME unusable:

280°-295° byd 25 NM blo 7,000'

310°-350° byd 25 NM blo 6,500'

•
HELIPAD H1: H20X20 (CONC)

HELIPAD H2: H20X20 (CONC)

SEATTLE
L-13A

