

COLUMBIA/MARION CO (ØRØ) 3 N UTC-6(-5DT) N31°17.87' W89°48.69'

NEW ORLEANS

270 B NOTAM FILE GWO

L-21B, 22F

RWY 05-23: H5500X100 (ASPH-GRVD) S-63, D-90, 2D-174

PCN 23 F/B/X/T MIRL 0.5% up NE

RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 42'. Trees.

RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 43'. Tree.

SERVICE: S2 **FUEL** 100LL, JET A **LGT** Actvt REIL Rwy 05 and 23;

MIRL Rwy 05-23—CTAF. PAPI Rwy 05 and 23 opr consly.

AIRPORT REMARKS: Attended on call. For svc call 601-441-0299 or 601-441-1867. Fuel svc avbl 24 hrs with credit card. Pub fone avbl 601-736-9295.

AIRPORT MANAGER: 601-736-9295

WEATHER DATA SOURCES: AWOS-3PT 120.675 (601) 736-4983.

COMMUNICATIONS: CTAF/UNICOM 122.8

® **HOUSTON CENTER APP/DEP CON** 126.8

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE GWO.

EATON (L) (L) VORTACW 110.6 LBY Chan 43 N31°25.12'

W89°20.26' 249° 25.4 NM to fld. 290/5E.

VOR unusable:

010°-036° byd 30 NM

010°-036° byd 6 NM blo 15,000'

111°-164° byd 10 NM blo 2,000'

241°-251°

300°-000° byd 30 NM

TACAN AZIMUTH unusable:

010°-036° byd 30 NM

010°-036° byd 6 NM blo 15,000'

300°-000° byd 30 NM

DME unusable:

268°-274° byd 30 NM blo 5,000'

300°-000° byd 30 NM

