246 OKLAHOMA

 TISHOMINGO AIRPARK
 (ØF9)
 2 S
 UTC-6(-5DT)
 N34°11.91′ W96°40.47′
 DALLAS-FT WORTH

 647
 B
 NOTAM FILE MLC
 L-17C
 L-17C

RWY 17-35: H3100X60 (ASPH) S-12 RWY LGTS(NSTD)

RWY 17: Trees.

RWY 35: Trees.


SERVICE: LGT Nstd solar LIRL Rwy 17–35 SS–SR. Rwy 17–35 nstd due to thild lgts all red and edge lgts all yellow. Rotating bcn OTS indef.

AIRPORT REMARKS: Unattended.
AIRPORT MANAGER: (580) 371-8605
COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Fort Worth ARTCC at 817-858-7584 RADIO AIDS TO NAVIGATION: NOTAM FILE ADM.

**ARDMORE (VH) (H) VORTACW** 116.7 ADM Chan 114 N34°12.70′ W97°10.09′ 086° 24.6 NM to fld. 937/6E.

VOR unusable: 150°-160° 302°-346°



## TULSA

**HARVEY YOUNG** (1H6) 8 E UTC-6(-5DT) N36°08.34′ W95°49.50′

KANSAS CITY

750 B NOTAM FILE MLC **RWY 17–35**: H2580X40 (ASPH)

RWY 17: Trees. RWY 35: Trees.

RWY N-S: 2580X80 (TURF)

RWY N: Trees. RWY S: Trees.

SERVICE: S2 FUEL 100LL

AIRPORT REMARKS: Attended Mon–Fri 1400–2300Z‡. Arpt unattended federal holidays. Birds on and invof airport. Ultralights on and invof arpt. Rwy 17 rgt tfc for helicopters. Twys thin & soft in hot weather. Rwy 17–35 severe cracking and raveling. Rwy 17 markings severely faded. Rwy 35 markings svrly faded; nos unrdbl. Rwy N/S rough and uneven.

AIRPORT MANAGER: 918-298-4044 COMMUNICATIONS: CTAF/UNICOM 122.8

CLEARANCE DELIVERY PHONE: For CD ctc Tulsa Apch at 918-831-6714/6720.