

IRAAN MUNI (2F0) 1 SE UTC-6(-5DT) N30°54.37' W101°53.39'

SAN ANTONIO

2200 B NOTAM FILE SJT

L-19A
RWY 14-32: H4085X60 (ASPH) S-12.5 RWY LGTS(NSTD)

RWY 14: Thld dsplcd 500'. P-line.

RWY 32: Thld dsplcd 490'.

RWY 07-25: H2755X50 (ASPH) S-12.5 0.9% up E

RWY 07: P-line.

RWY 25: Brush.

SERVICE: **FUEL** 100LL **LGT** Rwy 14-32 LIRL out of svc. Rwy 14-32 NSTD dspld thld lgts. Rwy 14-32 NSTD fixtures, not frangible, NSTD layout, NSTD colors.

AIRPORT REMARKS: Unattended. Wildlife on and invof arpt. Rising trm southwest and west of arpt. 110LL 24 hr self-serve.

Rwy 32, 15 ft drop off at rwy end. Rwy 07 and Rwy 25 markings are faded. Rwy 07-25 loose, extsv cracking, pot holes on cl. Rwy 14 and Rwy 32 thrs dsplcd not lgthd, day opns only. Also 35 ft p-line, 530 ft dist, apch ratio 9:1. Mkd with orange balls.

AIRPORT MANAGER: 432-639-2841

COMMUNICATIONS: **CTAF** 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Houston ARTCC at 281-230-5622.

RADIO AIDS TO NAVIGATION: NOTAM FILE FST.

FORT STOCKTON (VH) (H) VORTACW 116.9 FST Chan 116 N30°57.13' W102°58.54' 082° 56.1 NM to fld. 2893/11E.

VOR unusable:

020°-055° byd 20 NM blo 6,900'

070°-086° byd 35 NM blo 6,400'

106°-132° byd 30 NM blo 5,900'

125°-202° byd 40 NM

203°-213° byd 40 NM blo 18,000'

214°-230° byd 40 NM

245°-255° byd 40 NM

315°-330° byd 30 NM blo 5,400'

IRESH N31°01.45' W97°42.49' NOTAM FILE ILE.

SAN ANTONIO
NDB (LOMW) 278 IL 012° 3.9 NM to Skylark Fld. 853/5E.

L-19C, 21A

NDB unusable:

066°-294° byd 15 NM

295°-065° byd 5 NM due to military restricted area

IRONHEAD (See SANGER on page 434)

JACK BROOKS RGNL (See BEAUMONT/PORT ARTHUR on page 269)

JACKSBORO MUNI (21F) 1 NE UTC-6(-5DT) N33°13.67' W98°08.79'

DALLAS-FT WORTH

1062 B NOTAM FILE FTW

L-17C
RWY 18-36: H3220X75 (ASPH) S-4 MIRL 1.2% up S

RWY 18: Pole.

RWY 36: Trees.

SERVICE: **FUEL** 100LL

AIRPORT REMARKS: Unattended. Birds on and invof arpt. Arpt gate locked-combination 1581. Pilot lounge/restroom access

1200. 6 ft open drainage ditch near Rwy 18 thr, 81 ft east of cntrln on both sides of twy. 5 ft open drainage ditch 84 ft east of Rwy 18 cntrln on both sides of ramp south twy.

AIRPORT MANAGER: 940-507-3147

COMMUNICATIONS: **CTAF** 122.9

RCO 122.4 (FORT WORTH RADIO)

RADIO AIDS TO NAVIGATION: NOTAM FILE FTW.

BOWIE (H) (H) VORTACW 117.15 UKW Chan 118(Y) N33°32.15' W97°49.28' 216° 24.6 NM to fld. 1102/6E.

JACKSON CO (See EDNA on page 318)