

HANKSVILLE (HVE)(KHVE) 3 N UTC-7(-6DT) N38°25.17' W110°42.18'

4454 B NOTAM FILE HVE

RWY 09-27: H5001X75 (ASPH) S-12.5 PCN 4 F/D/X/T MIRL

RWY 09: PAPI(P4L)—GA 3.0° TCH 43'.

RWY 27: PAPI(P4L)—GA 3.0° TCH 42'.

RWY 17-35: 4841X120 (DIRT) 0.5% up N

SERVICE: LGT ACTIVATE PAPI Rwy 09 and Rwy 27; MIRL Rwy 09-27—CTAF.

AIRPORT REMARKS: Unattended. First 1000 ft of Rwy 17 soft. Rwy 17-35 unusbl S of Rwy 09-27, vegetation on rwy.

AIRPORT MANAGER: 503-847-7176

WEATHER DATA SOURCES: AWOS-3 120.0 (435) 542-1020.

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.3 (CEDAR CITY RADIO)

CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Salt Lake ARTCC at 801-320-2568.

RADIO AIDS TO NAVIGATION: NOTAM FILE HVE.

(VH) (H) **VORTACW** 115.9 HVE Chan 106 N38°25.01' W110°41.98' at fld. 4431/15E.

VOR unusable:

015°-025° byd 40 NM blo 18,000'

026°-065° byd 40 NM

030°-060° byd 25 NM blo 7,500'

160°-180° byd 15 NM blo 9,500'

160°-190° byd 40 NM

215°-220° byd 40 NM

221°-231° byd 40 NM blo 18,000'

232°-248° byd 40 NM

249°-259° byd 40 NM blo 16,000'

249°-259° byd 74 NM

260°-014° byd 40 NM

TACAN AZIMUTH unusable:

030°-060° byd 25 NM blo 7,500'

160°-180° byd 15 NM blo 9,500'

DME unusable:

030°-060° byd 25 NM blo 7,500'

160°-180° byd 15 NM blo 9,500'

HEBER VALLEY (HCR)(KHCR) 1 S UTC-7(-6DT) N40°28.91' W111°25.73'

5637 B NOTAM FILE CDC

RWY 04-22: H6898X75 (ASPH) S-30 PCN 32 F/B/X/T MIRL

0.8% up NE

RWY 22: PAPI(P4L)—GA 4.0° TCH 42'. Road.

SERVICE: S4 FUEL 100LL, JET A, J OX 1, 2 LGT ACTVT PAPI Rwy 22;

MIRL Rwy 04-22—CTAF. Rwy 22 PAPI unusbl byd 3.5 NM fm thld and byd 6 degs left and right of cntrl.

AIRPORT REMARKS: Attended May-Oct 1500-0130Z†, Nov-Apr

1500-0000Z†. Glider activity on and invof arpt. Balloon activity on and invof arpt. Birds on and invof arpt. Snow removal Nov-Apr. Small acft

prkg lctd south west of fuel farm. Rdo tmtn on sfc may not be rcvd at

opposite EOR. Comm intfc fm trrn invof apt, dep acft must tmt start of

taxi & depg rwy, parl twy hdg to depg rwy, & line up for dep. Acft

departing south-southwestbound be aware of high tfc volume

descending to 16,000 ft over SPANE intersection. Preferred calm wind

Rwy 22. Cold temperature airport. Altitude correction required at or

below -16C. Lndg fees: Tsnt acft ctc amgr. Expc FBO fee's ie: fac chrgs,

tie down fees etc. Fees are separte in addn to arpt lndg fees.

AIRPORT MANAGER: 435-657-7949

WEATHER DATA SOURCES: AWOS-3PT 124.825 (435) 657-0892.

COMMUNICATIONS: CTAF/UNICOM 122.8

® SALT LAKE CENTER APP/DEP CON 119.95

CLEARANCE DELIVERY PHONE: For CD ctc Salt Lake ARTCC at 801-320-2568.

SALT LAKE CITY

H-3D, L-9D, 11D

IAP

