

GILA BEND MUNI (E63) 2 E UTC-7 N32°57.61' W112°40.42'

789 B TPA—1589(800) NOTAM FILE PRC

PHOENIX
H-4J, L-5B, A

RWY 04-22: H5200X75 (ASPH) S-12.5 MIRL 0.3% up NE

RWY 04: PAPI(P2L)—GA 3.0° TCH 40'. Tree.

RWY 22: PAPI(P2L)—GA 3.0° TCH 40'. Tree.

SERVICE: FUEL 100LL LGT Actvt MIRL Rwy 04-22—CTAF. CTAF

lighting OTS indef. Airport lighted windsock out of service indef. Airport beacon out of service indef. Intens Rwy Lights: Rwy 04-22 and twy lighting system out of service indef.

AIRPORT REMARKS: Unattended. 100LL self svc H24 with credit card. Rwy 04-22 primary sfc, +5-20 ft brush and trees, 100-125 ft S of cntrln. Area parl rwy narrows to 30' at culvert. NOTE: See Special Notices—Restricted Area R-2305, Gila Bend, Arizona Transit Information.

AIRPORT MANAGER: 623-810-4662

COMMUNICATIONS: CTAF/UNICOM 122.8

RCO 122.1R 116.6T (PRESCOTT RADIO)

CLEARANCE DELIVERY PHONE: For CD ctc Luke Apch at 623-856-7361. If una ctc Albuquerque ARTCC at 505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE PRC.

(VH) (H) VORTAC 116.6 GBN Chan 113 N32°57.38'

W112°40.46' at fld. 790/14E.

TACAN AZIMUTH unusable:

360°-010° byd 25 NM

VOR unusable:

091°-101° byd 40 NM blo 18,000'

102°-114° byd 40 NM blo 6,500'

102°-114° byd 53 NM blo 15,000'

102°-114° byd 79 NM

115°-189° byd 40 NM

211°-213° byd 40 NM

287°-292° byd 40 NM

293°-303° byd 40 NM blo 18,000'

304°-331° byd 40 NM

352°-090° byd 40 NM

