

DUTCH LANDING STRIP (88AK) PVT	0 N	UTC-9(-8DT)	N60°32.42' W150°52.08'	ANCHORAGE
300 NOTAM FILE	Not insp.			
RWY 07-25: 1300X100 (GRVL)				
RWY 07: Trees.				
RWY 25: Trees. Rgt tfc.				
AIRPORT REMARKS: Unattended.				
AIRPORT MANAGER: 907-398-8999				
COMMUNICATIONS: CTAF 122.5				
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.				
LAKEWOOD AIRSTRIP (53AK) PVT	5 NE	UTC-9(-8DT)	N60°32.03' W150°51.39'	ANCHORAGE
299 NOTAM FILE	Not insp.			
RWY 02-20: 1200X60 (GRVL)				
RWY 02: Trees. Rgt tfc.				
AIRPORT REMARKS: Unattended. Rwy 02-20 not plowed durg winter, silty sand base unusbl durg breakup. Rwy 02-20 sand/gravel.				
AIRPORT MANAGER: 936-443-9072				
COMMUNICATIONS: CTAF 122.5				
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.				
SCOOTERS LANDING STRIP (AK84) PVT	2 W	UTC-9(-8DT)	N60°31.77' W150°49.85'	ANCHORAGE
259 NOTAM FILE	Not insp.			
RWY 08-26: 2400X80 (GRVL)				
AIRPORT REMARKS: Unattended. PPR arpt rstd to owner or owner invited guests. No acft svcs avbl. Rwy conditions not monitored. Fly pat south of E-W rwy, twrs north. Pilots to conduct rwy visual inspection prior to use. Maintenance personnel and equipment have right of way. Wildlife inovf rwy. Be alert, dsplcd thlds exist. Trees and p-lines penetrate apch sfcs. Arpt not fenced.				
AIRPORT MANAGER: 907-398-9849				
COMMUNICATIONS: CTAF 122.5				
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737. Advisory frequency: 122.5.				
STERLING AIR PARK (40AK) PVT	2 NW	UTC-9(-8DT)	N60°33.45' W150°50.61'	ANCHORAGE
333 NOTAM FILE	Not insp.			
RWY 08-26: 1809X60 (GRVL)				
AIRPORT REMARKS: Unattended.				
AIRPORT MANAGER: 907-262-5100				
COMMUNICATIONS: CTAF 122.5				
COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-866-864-1737.				
STEVENS VILLAGE (SVS)(PFSV)	1 NNE	UTC-9(-8DT)	N66°01.03' W149°03.26'	FAIRBANKS
328 B NOTAM FILE FAI				H-1B, L-4J
RWY 05-23: 4000X75 (GRVL-DIRT)	MIRL			
RWY 05: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.				
RWY 23: REIL. PAPI(P4L)—GA 3.0° TCH 25'. Trees.				
SERVICE: LGT ACTVT REIL Rwy 05 and 23; PAPI Rwy 05 and 23; MIRL Rwy 05-23—CTAF. ACTVT Rotg beacon—CTAF.				
AIRPORT REMARKS: Unattended. Rwy cond unrrnt; rcmd visual insp bfr lndg. Cld rwy 1 NM W. Snow removal ops—CTAF. Rwy 05-23 marked with lghts & cones.				
AIRPORT MANAGER: 907-451-5280				
COMMUNICATIONS: CTAF 122.9				
RADIO AIDS TO NAVIGATION: NOTAM FILE FAI.				
FAIRBANKS (H) (H) VORTACW 108.6 FAI Chan 23 N64°48.00'				
W148°00.72' 320° 77.8 NM to fld. 1526/21E.				
TACAN AZIMUTH unusable:				
065°-100° byd 30 NM				
270°-330° byd 10 NM bld 10,000'				
270°-330° byd 30 NM				
COMM/NAV/WEATHER REMARKS: For a toll free call to Fairbanks FSS dial 1-866-248-6516.				

