

JACKSON**JAMES A RHODES** (JRO)(KJRO) 5 SE UTC-5(-4DT) N38°58.88' W82°34.67'


726 B NOTAM FILE JRO

RWY 01-19: H5201X75 (ASPH) MIRL**RWY 01:** PAPI(P4R)—GA 4.0° TCH 45'. Thld dspld 331'. Tree.**RWY 19:** PAPI(P4L)—GA 4.0° TCH 45'. Road.**SERVICE:** S4 **FUEL** 100LL, JET A1+ **LGT** ACTIVATE MIRL Rwy 01-19—CTAF. PAPI Rwy 01 & 19 opr consly. Rwy 01 PAPI unusbl byd 9 degs left of cntrln. Rwy 19 PAPI unusbl byd 7 degs right of cntrln.**AIRPORT REMARKS:** Attended Mon-Fri 1300-1900Z+. Fuel avbl H24 self svc via credit card.**AIRPORT MANAGER:** 740-286-0137**WEATHER DATA SOURCES:** AWOS-3PT 118.825 (740) 286-1760.**COMMUNICATIONS:** CTAF/UNICOM 122.7® **HUNTINGTON APP/DEP CON** 128.4**CLEARANCE DELIVERY PHONE:** For CD ctc Huntington ATCT at 304-453-2490.**RADIO AIDS TO NAVIGATION:** NOTAM FILE EKN.**HENDERSON (H) DME** 115.9 HNN Chan 106 N38°45.25'

W82°01.57' 298° 29.2 NM to fld. 880.

DME unusable:

185°-290° blo 4,500'

**JAMES A RHODES** (See JACKSON on page 293)**JAMES M COX DAYTON INTL** (See DAYTON on page 283)**JEFFERSON** N41°45.61' W80°44.89' NOTAM FILE CLE.(L) **DME** 115.2 JFN Chan 99 065° 2.5 NM to Northeast Ohio Rgnl. 896.

DME unusable:

120°-255°

355°-050°

DETROIT

L-30G

JOHN GLENN COLUMBUS INTL (See COLUMBUS on page 277)**KELLEYS ISLAND LAND FLD** (89D) 1 NE UTC-5(-4DT) N41°36.19' W82°41.10'

598 NOTAM FILE CLE

RWY 09-27: H2202X50 (ASPH) MIRL 0.9% up W**RWY 09:** Thld dspld 200'. Trees.**RWY 27:** Fence.**SERVICE:** **LGT** Actvt MIRL Rwy 09-27—CTAF**AIRPORT REMARKS:** Unattended. Deer and birds on and invov arpt. Landing fee.**AIRPORT MANAGER:** 419-503-0663**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Cleveland Apm at 216-352-2323.**DETROIT**