

SIDNEY MUNI (SCA)(KSCA) 3 S UTC-5(-4DT) N40°14.48' W84°08.87'**DETROIT**

1044 B TPA—1844(800) NOTAM FILE DAY

H-10G, L-27E**RWY 10-28:** H5013X75 (ASPH) MIRL**IAP****RWY 10:** REIL. PAPI(P2L)—GA 3.0° TCH 42'. Crops.**RWY 28:** REIL. PAPI(P2L)—GA 3.0° TCH 36'. Crops.**RWY 05-23:** H2981X50 (ASPH)**RWY 23:** Crops.**SERVICE:** S4 **FUEL** 100LL, JET A **OX 1** **LGT** Actvt REIL Rwy 10 and 28; MIRL Rwy 10-28—CTAF. PAPI Rwy 10 and 28 opr consly.**AIRPORT REMARKS:** Attended Mon—Sat 1300-2300Z†. 100LL and Jet A avbl H24 via credit card. Jet A anti-icing additive avbl at nozzle. Rwy 10 and 28 faded exc rwy nr.**AIRPORT MANAGER:** 937-492-9794**WEATHER DATA SOURCES:** AWOS-3 120.425 (937) 492-3683.**COMMUNICATIONS:** CTAF/UNICOM 123.05® **COLUMBUS APP/DEP CON** 134.45**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.**ROSEWOOD (H) (H) VORTACW** 117.5 **ROD** Chan 122 N40°17.27' W84°02.59' 245° 5.6 NM to fld. 1080/5W.**TACAN AZIMUTH** unusable:

000°-120°

125°-135°

VOR unusable:

125°-135°

SPORTYS N39°04.60' W84°12.92' NOTAM FILE DAY.**CINCINNATI****NDB (MHW)** 245 **PWF** at Clermont Co. 850/4W.**L-27E****NDB** unusable:

Byd 15 NM

SPRINGFIELD/BECKLEY MUNI (SGH)(KSGH) P (ANG) 5 S UTC-5(-4DT) N39°50.42' W83°50.41'**CINCINNATI**

1051 B TPA—See Remarks NOTAM FILE SGH

H-10G, L-27E**RWY 06-24:** H9010X150 (ASPH-CONC-GRVD) S-66, D-175, 2D-330**IAP, DIAP, AD****PCN** 60 R/B/W/T **HIRL****RWY 06:** REIL. PAPI(P4L)—GA 3.0° TCH 45'. Trees.**RWY 24:** SSALR. PAPI(P4L)—GA 3.0° TCH 60'. Tree.**RWY 15-33:** H5498X100 (ASPH) S-35, D-50 **MIRL****RWY 15:** REIL. PAPI(P4L)—GA 3.0° TCH 36'. Crops.**RWY 33:** REIL. PAPI(P4L)—GA 3.0° TCH 37'. Trees.**RUNWAY DECLARED DISTANCE INFORMATION****RWY 06:** TORA-9009 TODA-9009 ASDA-9009 LDA-9009**RWY 15:** TORA-5499 TODA-5499 ASDA-5499 LDA-5499**RWY 24:** TORA-9009 TODA-9009 ASDA-9009 LDA-9009**RWY 33:** TORA-5499 TODA-5499 ASDA-5499 LDA-5499**SERVICE:** S4 **FUEL** 100LL, JET A+ **OX 1, 4** **LGT** ACTVT wind cone;

SSALR Rwy 24; REIL Rwy 06, 15 & 33; HIRL Rwy 06-24; MIRL Rwy

15-33—CTAF. PAPI Rwy 06, 24, 15, & 33 opr consly. Rwy 15 PAPI

unusbl byd 9 degs right of cntrln. Rwy 24 ALS unmon indefly.

NOISE: Noise abatement: Avoid overflying Yellow Springs 2 NM SW blw 4000 ft.**AIRPORT REMARKS:** Attended Mon-Fri 1230-2300Z†, Sat-Sun

1400-2200Z†. Ocnl deer, birds and otr wildlife on and invof arpt. Hvy

bird activity drg fall and winter months. FBO svcs avbl on freq 120.7. Rwy 24 is pref wind rwy 10 kt or less. Avoid

overflying ANG ramp. Rwy 06-24 980' concrete NE end, 1200' concrete SW end. TPA—2100 (1049), ohd TPA 2600 (1549).

AIRPORT MANAGER: 937-325-6108**WEATHER DATA SOURCES:** AWOS-3PT 134.975 (937) 324-4532.**COMMUNICATIONS:** CTAF/UNICOM 122.95® **COLUMBUS APP/DEP CON** 118.85 269.275**CLEARANCE DELIVERY PHONE:** For CD ctc Columbus Apch at 614-338-8537.**RADIO AIDS TO NAVIGATION:** NOTAM FILE DAY.(T) **TACAN** Chan 65 **XSf** (133.8) N39°50.29' W83°50.44' at fld. 1052/4W. unmonitored when twr clsd. No

NOTAM MP: 1330-1530Z† Thu.

TACAN AZ unusable:

090°-115° byd 15 NM

(T) **DME** 113.2 **SGH** Chan 79 N39°50.19' W83°50.70' at fld. 1046. NOTAM FILE SGH.**DME** unusable:

150°-160° byd 14 NM blo 5,000'

