

BIDDEFORD MUNI (B19) 2 S UTC-5(-4DT) N43°27.85' W70°28.34'

NEW YORK

157 B TPA—995(838) NOTAM FILE BGR

L-32H

RWY 06-24: H3000X75 (ASPH) S-25 MIRL 0.3% up NE

IAP

RWY 06: REIL. PAPI(P4L)—GA 3.5° TCH 31'. Brush.

RWY 24: Brush.

SERVICE: FUEL 100LL LGT Actvt REIL Rwy 06; PAPI Rwy 06; MIRL

Rwy 06-24—CTAF.

NOISE: Noise abatement ctc AMGR for dtls.

AIRPORT REMARKS: Attended Mon–Thur 1500–2100Z†, Sat–Sun

1400–2100Z†. Deer and turkeys on and in/ovf arpt. Ultralight and prcht act on and in/ovf arpt. 24 hr fuel w/major credit card–self svc.

Rwy 24 calm wind rwy.

AIRPORT MANAGER: 207-282-1579

COMMUNICATIONS: CTAF/UNICOM 123.0

Ⓡ **PORTLAND APP/DEP CON** 119.75 (1045-0500Z†)

Ⓡ **BOSTON CENTER APP/DEP CON** 128.2 (0500-1045Z†)

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.

RADIO AIDS TO NAVIGATION: NOTAM FILE BGR.

KENNEBUNK (VH) (DH) VORW/DME 117.1 ENE Chan 118

N43°25.54' W70°36.81' 086° 6.6 NM to fld. 192/17W.

DME unusable:

030°–184° byd 25 NM blo 2,000'

185°–230° byd 25 NM blo 2,500'

268°–278° byd 30 NM blo 4,600'

VOR unusable:

017°–040° byd 40 NM

130°–133° byd 40 NM

192°–202° byd 40 NM blo 2,500'

192°–202° byd 48 NM blo 5,000'


192°–202° byd 69 NM

203°–294° byd 40 NM

295°–305° byd 40 NM blo 5,000'

295°–305° byd 52 NM

306°–359° byd 40 NM



BOWDOINHAM

MERRYMEETING FLD (Ø8B) 1 SE UTC-5(-4DT) N44°00.00' W69°53.23'

MONTREAL

61 NOTAM FILE BGR

RWY 14-32: 1935X100 (TURF)

RWY 14: Thld dsplcd 425'. Trees.

RWY 32: Thld dsplcd 143'. Trees.

AIRPORT REMARKS: Attended irregularly. Call for rwy conditions prior to ldg. Wildlife on or in/ovf arpt. Winter ops (Nov 1–May

1) skis only, rwy not plowed. Rwy 14 has +15' roadway 95' rgt and +15' building 125' left at thld. No line of sight between rwy ends.

AIRPORT MANAGER: 781-864-7011

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at 603-879-6859.

BOWMAN FLD (See LIVERMORE FALLS on page 74)

BRADFORD CAMPS SPB (See ASHLAND on page 56)

BREWER (ØB2) 2 S UTC-5(-4DT) N44°45.83' W68°46.07'

HALIFAX

125 TPA—725(600) NOTAM FILE BGR

RWY 01-19: 1730X30 (TURF) 0.3% up N

RWY 01: Brush. Rgt tfc.

RWY 19: Trees.

SERVICE: S2

AIRPORT REMARKS: Unattended. +25 ft power line 460ft N of Rwy 19 end. Rwy 01-19 +35 ft trees and brush 30 ft to 125 ft from centerline along east side. Rwy 19 +25 ft house 80 ft from thr, 50 ft right of cntrln. Wildlife on or in/ovf arpt. Public golf course at EOR 01. During winter ski only ops. Make all apch/deps to east of arpt. Rwy 01-19 cntr 50 ft mowed.

AIRPORT MANAGER: 207-299-4086

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2500 extn 1.