

STONINGTON MUNI (93B) 1 NW UTC-5(-4DT) N44°10.39' W68°40.82' HALIFAX
32 NOTAM FILE BGR
RWY 07-25: H2099X60 (ASPH) 0.3% up W
RWY 07: Trees.
RWY 25: Trees. Rgt t/c.
AIRPORT REMARKS: Unattended. Dalgt use only. Use extreme care seagulls and deer on and invof arpt. Trees and brush in pri
sfc some as close as 50 ft fm cntrln. Rwy 07 nrs and cntrln non-std and faded. Rwy 25 nrs and cntrln non-std.
AIRPORT MANAGER: 207-367-2351
COMMUNICATIONS: CTAF 122.9
Ⓡ BANGOR APP/DEP CON 133.6
CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2500 extn 1.
• • • • •
HELIPAD H1: H40X40 (ASPH)

SUGARLOAF RGNL (See CARRABASSETT on page 64)

SWANS ISLAND

BANKS (ME5) 5 N UTC-5(-4DT) N44°09.92' W68°25.69' HALIFAX
100 NOTAM FILE BGR
RWY 10-28: 1500X30 (GRVL) 2.0% up W
RWY 10: Tree.
RWY 28: Thld dsplcd 300'. Tree.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 10: TORA-1500 TODA-1500 ASDA-1500 LDA-1500
RWY 28: TORA-1500 TODA-1500 ASDA-1500 LDA-1200
AIRPORT REMARKS: Unattended. Prior to using arpt call 207-460-1113. All ops rstrd to dalgt VFR only. Wildlife on and invof
arpt. Rwy 10-28 +6 ft rock ledge 50 ft from centerline, south side of arpt. Rwy 10: +20 ft trees 50 ft R of cntrln, 430
ft fm thr. Rwy 10-28 sfc rough with lrg stones, steep gradients and no line of sight between ends. Rock drainage swale
across 600 ft from Rwy 28 thr, approximately 40 ft wide at centerline. Com twr 500 ft AGL, 1 mi SE of rwy.
AIRPORT MANAGER: 207-460-1113
COMMUNICATIONS: CTAF 122.9
Ⓡ BANGOR APP/DEP CON 133.6
CLEARANCE DELIVERY PHONE: For CD ctc Bangor Apch at 207-561-2500 extn 1.
• • • • •
HELIPAD H1: H40X40 (CONC)
HELIPORT REMARKS: Helipad coords 44 09 54.80N 68 25 48.80W; helipad elev 86'. Ingress and egress to helipad between
130° and 320° mag.

VAN BUREN SPB (Ø5B) 0 N UTC-5(-4DT) N47°09.54' W67°55.92' HALIFAX
440 LRA NOTAM FILE BGR
WATERWAY NW-SE: 4000X200 (WATER)
WATERWAY SE: Bridge.
SEAPLANE REMARKS: Unattended. Clsd Oct 15-May 15 yearly. Dock located near base of bridge. Flight Notification Service
(ADCUS) available. U.S. Customs avbl 24 hrs, 207-868-3391.
AIRPORT MANAGER: 207-868-2886
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Boston ARTCC at 603-879-6859.

WALES (ME6) 2 SSW UTC-5(-4DT) N44°10.47' W70°01.14' MONTREAL
210 NOTAM FILE BGR
RWY 04-22: 2100X80 (TURF)
RWY 04: Ground.
RWY 22: Tree.
AIRPORT REMARKS: Unattended. Arpt CLOSED Nov-May, exc for skiing. Rwy 04-22 soft in spring. Acft should mnt 122.8 invof
arpt. 1239' MSL twr 7000' SE and 968' MSL twr 9600' SSE of arpt. Rwy 04-22 nstd markings, has white plastic
barrel markers along side of rwy with thld marked with single plastic white barrel. FCLP equipment directly adjacent to
left side of Rwy 10 1335-1725' approach end. FCLP equipment directly adjacent to left side of Rwy 28 1340-1725'
from approach end.
AIRPORT MANAGER: 207-754-6322
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Portland Apch at 207-874-7320, when Apch clsd ctc Boston ARTCC at
603-879-6859.