

WARDEN (2S4) 1 W UTC-8(-7DT) N46°57.95' W119°03.98'

1276 B NOTAM FILE SEA

RWY 17-35: H2811X60 (ASPH) MIRL

RWY 17: SAVASI(S2R). Thld dsplcd 560'.

SERVICE: LGT SS-SR.


AIRPORT REMARKS: Unattended. CAUTION: Structures and irrigation material in pri apch sfc. Roads parl both sides of rwy. Rwy 17-35 320' grvl ovrn south end. Rwy 17-35 centerline paint chipping. No rwy numbers. Grvl apron cond good. Pilots bring own ropes.

AIRPORT MANAGER: 509-750-4634

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

SEATTLE



WATERVILLE (2S5) 1 NE UTC-8(-7DT) N47°39.36' W120°03.39'

2645 B NOTAM FILE SEA

RWY 07-25: H2978X50 (ASPH) S-5 LIRL

RWY 07: Thld dsplcd 270'. Road.

RUNWAY DECLARED DISTANCE INFORMATION

RWY 07: TORA-2800 TODA-2800 LDA-2500

RWY 25: TORA-2500 TODA-2500 LDA-2500


AIRPORT REMARKS: Unattended. Hill on S side of rwy in tran sfc. Rwy shoulders soft in wet weather.

AIRPORT MANAGER: 509-884-4700

COMMUNICATIONS: CTAF 122.9

CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

SEATTLE



WATON N48°04.57' W122°09.23' NOTAM FILE AWO.

NDB (LOMW) 382 AW 341° 5.1 NM to Arlington Muni. 65/17E.

SEATTLE