
RANCHO MURIETA (RIU)(KRIU) 1 W UTC-8(-7DT) N38°29.21' W121°06.17' SAN FRANCISCO
 144 TPA—944(800) NOTAM FILE RIU L-2F, 3A
RWY 04-22: H3798X75 (ASPH)
RWY 04: VASI(V2L)—GA 3.0° TCH 12'. Road. Rgt tfc.
RWY 22: VASI(V2L)—GA 3.0° TCH 12'. Tree.
SERVICE: **FUEL** 100LL, JET A **LGT** Rwy 04 VASI OTS indef. Arpt lgts opr 1600-0100Z†.
NOISE: Rwy 22 noise abatement procedures in effect, ctc arpt manager 916-354-2940.
AIRPORT REMARKS: Attended 1600-0100Z†. Deer on and invof rwy. +30' obstruction lit power poles parallel to Rwy 04-22.
 All ultralights must comply with FAR 103 and have an operating acft radio. All transient acft rqrd to park in designated transient area. Ldg fees apply. Pstn single \$25, pstn twin \$40, turbo prop \$75, jet \$100.
AIRPORT MANAGER: 916-354-2940
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc NorCal Apch at 916-361-6874.
RADIO AIDS TO NAVIGATION: NOTAM FILE SAC.
SACRAMENTO (VH) (H) VORTACW 115.2 SAC Chan 99 N38°26.62' W121°33.10' 066° 21.3 NM to fld. 3/17E.
 VOR unusable:
 031°-041° byd 40 NM blo 5,000'
 031°-041° byd 45 NM blo 18,000'
 157°-169° byd 40 NM blo 4,500'
 157°-169° byd 56 NM blo 18,000'
 246°-251° byd 40 NM
 252°-262° byd 40 NM blo 7,000'
 252°-262° byd 65 NM
 263°-269° byd 40 NM
 353°-013° byd 40 NM blo 5,000'
 353°-013° byd 49 NM blo 5,500'
 353°-013° byd 58 NM

RAND MOUNTAIN N35°20.32' W117°41.02' LOS ANGELES
 RCO 122.4 (RIVERSIDE RADIO) L-7C

RAVENDALE (O39) 0 N UTC-8(-7DT) N40°48.22' W120°21.97' KLAMATH FALLS
 5306 TPA—6106(800) NOTAM FILE RNO
RWY 17-35: H2607X30 (ASPH)
RWY 35: Thld dsplcd 394'. Pole.
AIRPORT REMARKS: Unattended. Unpaved areas extremely soft when wet.
AIRPORT MANAGER: 530-251-8289
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Oakland ARTCC at 510-745-3380.
