

CONCHAS DAM**CONCHAS LAKE** (E89) 1 SW UTC-7(-6DT) N35°22.07' W104°10.83'**ALBUQUERQUE**

4232 B NOTAM FILE ABQ

L-15A

RWY 09-27: H4800X60 (ASPH) S-13 PCN 5 F/D/Y/T RWY

LGTS(NSTD) 0.9% up W

RWY 09: ODALS.**RWY 27:** ODALS.**SERVICE:** LGT Rwy 09-27 edge intens rwy lgts: reflective mkr. Rwy 09 ODALS: NSTD; one ODAL illuminates. Rwy 27 ODALS: NSTD; OTS indefly. ACTVT ODALS Rwy 09 and Rwy 27-CTAF.**AIRPORT REMARKS:** Unattended. Wildlife on and invof arpt. Gate aces 4230.

Twys have retro reflective mkr. Survey mkr 275 ft fm thr 55 ft left of cntrln.

AIRPORT MANAGER: 505-365-3891**COMMUNICATIONS:** CTAF 122.9

RCO 122.6 (ALBUQUERQUE RADIO)

CLEARANCE DELIVERY PHONE: For CD ctc Albuquerque ARTCC at

505-856-4861.

RADIO AIDS TO NAVIGATION: NOTAM FILE TCC.**TUCUMCARI (VH) (H) VORTACW** 113.6 TCC Chan 83 N35°10.93'

W103°35.91' 279° 30.7 NM to fld. 4035/12E.

VOR unusable:

125°-174° byd 40 NM

175°-193° byd 40 NM blo 12,500'

194°-227° byd 40 NM

228°-238° byd 40 NM blo 11,000'

228°-238° byd 46 NM

239°-249° byd 40 NM


250°-261° byd 40 NM blo 7,700'

250°-261° byd 46 NM blo 18,000'

262°-273° byd 40 NM

274°-284° byd 40 NM blo 18,000'

285°-355° byd 40 NM

**CONCHAS LAKE SPB** (E61) 2 SW UTC-7(-6DT) N35°23.05' W104°12.98'**ALBUQUERQUE**

4201 NOTAM FILE ABQ

WATERWAY ALL-WAY: 21120X1320 (WATER)**SEAPLANE REMARKS:** Unattended. Hvy boat tfc May-Oct. Water level fluctuates 4153-4201 ft; Indg haz due to exposed snags and land masses blw 4175 ft; mnt water level - 575-868-22221 or USCGS website under Conchas Lake. Ops NA north of the dam. Wind warning lgt W of dam at lodge; lgts flash grt than 20 mph wind. Exp SW wind; rcmdnd Indg and tkof to the W.**AIRPORT MANAGER:** 575-868-2221**COMMUNICATIONS:** CTAF 122.9**CLEARANCE DELIVERY PHONE:** For CD ctc Albuquerque ARTCC at 505-856-4861.**CONCHAS LAKE SPB** (See CONCHAS DAM on page 437)**CONCHAS LAKE** (See CONCHAS DAM on page 437)