

**NORTON MUNI** (NRN)(KNRN) 1 N UTC-6(-5DT) N39°51.03' W99°53.68'

**WICHITA**  
L-10H  
IAP

2384 B NOTAM FILE ICT

**RWY 16-34:** H4701X60 (CONC) HIRL 0.5% up NW

**RWY 16:** REIL. PAPI(P2L)—GA 3.0° TCH 44'.

**RWY 34:** REIL. PAPI(P2L)—GA 3.0° TCH 43'.

**RWY 08-26:** 2117X125 (TURF)

**RWY 08:** Trees.

**SERVICE:** FUEL 100LL, JET A, A1+ LGT HIRL Rwy 16-34 opr consly.

ACTVT PAPI Rwy 16 and 34—CTAF.

**AIRPORT REMARKS:** Attended Mon-Fri 1400-2300Z†. Fuel 24 hr self-serve. No line of sight between rwy ends. Rwy 08-26 sfc rough.

Rwy 16-34 rwy sfc rough due to uneven paving joints every 10 ft.

**AIRPORT MANAGER:** 785-877-2201

**WEATHER DATA SOURCES:** AWOS-3PT 118.275 (785) 871-4009.

**COMMUNICATIONS:** CTAF 122.9

® DENVER CENTER APP/DEP CON 132.7

**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE HLC.

**HILL CITY (VH) (H) VORTACW** 113.7 HLC Chan 84 N39°15.52'


W100°13.55' O15° 38.7 NM to fld. 2690/8E.

VOR unusable:

271°-274° byd 40 NM

279°-289° byd 40 NM blo 4,800'

279°-289° byd 47 NM



**NORWICH** (49K) 1 E UTC-6(-5DT) N37°27.33' W97°50.02'

**WICHITA**

1494 NOTAM FILE ICT

**RWY 17-35:** 3230X80 (TURF) LIRL(NSTD)

**RWY 17:** P-line.

**RWY 35:** Thld dspcld 180'. Railroad.

**SERVICE:** LGT NSTD LIRL Rwy 17-35, incorrect spacing.

**AIRPORT REMARKS:** Unattended. Rwy 35 dspcld thld marked with 2 lgts either side with painted tires. Irrigation pump and fuel tank 75' left of centerline Rwy 17 150' S of thld.

**AIRPORT MANAGER:** 620-704-3339

**COMMUNICATIONS:** CTAF 122.9

**CLEARANCE DELIVERY PHONE:** For CD ctc Wichita Apch at 316-350-1520.

**OAKLEY MUNI** (OEL)(KOEL) 2 SE UTC-6(-5DT) N39°06.71' W100°49.01'

**WICHITA**  
H-5B, L-10G  
IAP

3045 B NOTAM FILE ICT

**RWY 16-34:** H5000X75 (CONC) S-30 MIRL 0.5% up NW

**RWY 16:** REIL. PAPI(P2L)—GA 3.0° TCH 44'. Bldg.

**RWY 34:** REIL. PAPI(P2L)—GA 3.0° TCH 44'.

**RWY 08-26:** 2153X110 (TURF)

**RWY 26:** Road.

**RUNWAY DECLARED DISTANCE INFORMATION**

**RWY 16:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000

**RWY 34:** TORA-5000 TODA-5000 ASDA-5000 LDA-5000

**SERVICE:** S4 FUEL 100LL, JET A, A1+ LGT ACTVT REIL Rwy 16 and

Rwy 34; PAPI Rwy 16 and Rwy 34; MIRL Rwy 16-34—CTAF. Rwy

16 PAPI unusable byd 8° right and 6° left of centerline. Rwy 34 PAPI

unusable beyond 8° left of centerline.

**AIRPORT REMARKS:** Attended Mon-Fri 1400-2300Z†. For svc after hrs call 785-672-0147. Fuel 24 hrs self-serve.

**AIRPORT MANAGER:** 785-672-0147

**WEATHER DATA SOURCES:** AWOS-3 118.325 (785) 671-4194.

**COMMUNICATIONS:** CTAF/UNICOM 122.8

® DENVER CENTER APP/DEP CON 132.7

**CLEARANCE DELIVERY PHONE:** For CD ctc Denver ARTCC at 303-651-4257.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE HLC.

**HILL CITY (VH) (H) VORTACW** 113.7 HLC Chan 84 N39°15.52' W100°13.55' 244° 28.9 NM to fld. 2690/8E.

VOR unusable:

271°-274° byd 40 NM

279°-289° byd 40 NM blo 4,800'

279°-289° byd 47 NM

