



WARDEN (2S4) 1 W UTC-8(-7DT) N46°57.95' W119°03.98'
 1276 B NOTAM FILE SEA
RWY 17-35: H2811X60 (ASPH) MIRL
RWY 17: SAVASI(S2R). Thld dspcd 560'.
SERVICE: LGT SS-SR.
AIRPORT REMARKS: Unattended. CAUTION: Structures and irrigation material in pri apch sfc. Roads parll both sides of rwy. Rwy 17-35 320' grvl ovrn south end. Rwy 17-35 centerline paint chipping. No rwy numbers. Grvl apron cond good. Pilots bring own ropes.
AIRPORT MANAGER: 509-750-4634
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Grant County Apch at 509-762-2842, when Apch clsd ctc Seattle ARTCC at 253-351-3694.

SEATTLE



WATERVILLE (2S5) 1 NE UTC-8(-7DT) N47°39.36' W120°03.39'
 2645 B NOTAM FILE SEA
RWY 07-25: H2978X50 (ASPH) S-5 LIRL
RWY 07: Thld dspcd 270'. Road.
RUNWAY DECLARED DISTANCE INFORMATION
RWY 07: TORA-2800 TODA-2800 LDA-2500
RWY 25: TORA-2500 TODA-2500 LDA-2500
AIRPORT REMARKS: Unattended. Hill on S side of rwy in tran sfc. Rwy shouldered soft in wet weather.
AIRPORT MANAGER: 509-884-4700
COMMUNICATIONS: CTAF 122.9
CLEARANCE DELIVERY PHONE: For CD ctc Seattle ARTCC at 253-351-3694.

SEATTLE



WATON N48°04.57' W122°09.23' NOTAM FILE AWO.
NDB (LOWW) 382 AW 341° 5.1 NM to Arlington Muni. 65/17E.

SEATTLE