

KINSTON RGNL JETPORT AT STALLINGS FLD (ISO)(KISO) 3 NW UTC-5(-4DT) N35°19.89' CHARLOTTE
 W77°36.53' H-9C, 12H, L-35B
 IAP, AD
 93 B Class I, ARFF Index A NOTAM FILE ISO
RWY 05-23: H11498X150 (ASPH-GRVD) S-120, D-219, 2S-175, 2D-404, 2D/2D2-901
 PCN 53 F/A/W/T HIRL
RWY 05: MALSR, PAPI(P4L)—GA 3.0° TCH 60'. RVR-T Thld dsplcd 538'.
RWY 23: REIL, PAPI(P4L)—GA 3.0° TCH 74'. RVR-R Pole.
SERVICE: S4 FUEL 100LL, JET A LGT When ATCT clsd ACTVT MALSR Rwy 05; REIL Rwy 23; HIRL Rwy 05-23—CTAF.
 PAPI 23 opr consly.
AIRPORT REMARKS: Attended 1130-0300Z†. Clsd to unscheduled air carrier opr with more than 30 pax seats exc 24 hr PPR
 call arprt mgr 252-523-1351.
AIRPORT MANAGER: 252-607-0781
WEATHER DATA SOURCES: AWOS-3 132.75 (252) 522-2712. LAWRS.
COMMUNICATIONS: CTAF 120.6 UNICOM 122.95
 KINSTON RCO 122.15R 117.5T (RALEIGH RADIO)
 (R) SEYMOUR JOHNSON APP/DEP CON 127.3 (1200-0400Z†) other times ctc
 (R) WASHINGTON CENTER APP/DEP CON 123.85
 TOWER 120.6 (1130-0300Z†) GND CON 121.9
CLEARANCE DELIVERY PHONE: For CD if una to ctc on FSS freq, ctc Washington ARTCC at 703-771-3587.
AIRSPACE: CLASS D svc 1130-0300Z†; other times CLASS G.
RADIO AIDS TO NAVIGATION: NOTAM FILE ISO.
(VL) (L) VORTAC 117.5 ISO Chan 122 N35°22.26' W77°33.50' 231° 3.4 NM to fld. 70/5W.
 VOR unusable:
 020°-025° byd 40 NM
 040°-115° byd 40 NM
 145°-155° byd 40 NM
 175°-185° byd 40 NM
 183°-215° byd 30 NM blo 5,000'
 200°-206° byd 40 NM
 207°-214° byd 59 NM
 215°-238° blo 3,500'
 215°-238° byd 6 NM
 238°-258° byd 30 NM blo 5,000'
 239°-265° byd 40 NM
 280°-290° byd 40 NM
 295°-308° byd 40 NM
 309°-319° byd 31 NM
 320°-325° byd 40 NM
 335°-340° byd 40 NM
 345°-347° byd 40 NM
 348°-358° byd 20 NM
 TACAN AZIMUTH unusable:
 183°-215° byd 30 NM blo 5,000'
 DME unusable:
 183°-215° byd 30 NM blo 5,000'
 ILS/DME 111.3 I-ISO Chan 50 Rwy 05. Class IB. ILS mnt full-time.

KNIGHTDALE

RALEIGH EAST (W17) 2 E UTC-5(-4DT) N35°47.86' W78°26.22' CHARLOTTE
 313 B NOTAM FILE RDU L-35B, 36F
RWY 01-19: H3000X36 (ASPH) S-4 LIRL(NSTD)
RWY 01: Trees.
RWY 19: Bldg.
SERVICE: LGT Nstd LIRL, thld lgts are white, Rwy 19 lgtd thld relocated 70', 2930' of Rwy 01-19 unusbl at night, edge
 lgts are 17' fm rwy edge.
AIRPORT REMARKS: Attended irregularly. VFR only. Rwy 01-19 rolling pavement and cracks. Rwy 19 thld aprxly 40' higher
 than Rwy 01 thld (slps uphill to the north). Rwy 19 has 60' plines 1000' fm thld both sides of cntrln. Rwy 01-19 nstd
 small markings. Rwy 19 safety area has +20' bldgs and parked acft. +10' terrain 20' from rwy edge west side south
 2/3 of rwy. +5' terrain 20' from rwy edge west side of 2/3 of rwy.
AIRPORT MANAGER: 919-673-4527
COMMUNICATIONS: CTAF/UNICOM 122.8
CLEARANCE DELIVERY PHONE: For CD ctc Raleigh Apch at 919-380-3144.
RADIO AIDS TO NAVIGATION: NOTAM FILE RDU.
RALEIGH/DURHAM (H) (H) VORTACW 117.2 RDU Chan 119 N35°52.35' W78°47.00' 114° 17.5 NM to fld.
 429/9W.

LAKE NORMAN AIRPARK (See MOORESVILLE on page 339)