

## WHITEVILLE

COLUMBUS CO RGNL (CPC)(KCPC) 3 S UTC-5(-4DT) N34°16.37' W78°42.90'

CHARLOTTE  
H-9C, 12H, L-35A  
IAP

99 B NOTAM FILE CPC

RWY 06-24: H5500X75 (ASPH) S-45, D-60 MIRL 0.5% up SW

RWY 06: REIL. PAPI(P2L)—GA 3.0° TCH 40'. Trees.

RWY 24: REIL. PAPI(P2L)—GA 3.25° TCH 42'. Trees.

SERVICE: FUEL 100LL, JET A1+ LGT ACTVT REIL Rwy 06 &amp; 24;

MIRL Rwy 06-24—CTAF. PAPI Rwy 06 &amp; 24 on consly.

AIRPORT REMARKS: Attended Mon-Sat 1300-2300Z†, Sun 1400-2300Z†. Deer and turkeys on and invof arpt. Fuel 24 hr credit card svc avbl. For emergency service after hrs call 910-654-3389 or 910-625-5489. Arpt unatndd Easter Sunday, 4th July, Thanksgiving Day, Christmas Eve and Christmas Day. No off-pavement ldg allowed.

AIRPORT MANAGER: 910-642-6187

WEATHER DATA SOURCES: AWOS-3 118.375 (910) 642-7508.

COMMUNICATIONS: CTAF/UNICOM 122.8

Ⓜ MYRTLE BEACH APP/DEP CON 119.2 (1100-0400Z†)

Ⓜ JACKSONVILLE CENTER APP/DEP CON 134.375 (0400-1100Z†)

CLEARANCE DELIVERY PHONE: For CD ctc Myrtle Beach Apch at 843-477-2727 or 843-477-2704, when Apch clsd ctc Jacksonville ARTCC at 904-845-1592.

RADIO AIDS TO NAVIGATION: NOTAM FILE FLO.

FLORENCE (H) (H) VORTACW 115.2 FLO Chan 99 N34°13.98'

W79°39.43' 090° 46.9 NM to fld. 104/3W.

TACAN AZIMUTH unusable:

240°-285° byd 30 NM blo 4,000'

VOR unusable:

000°-017° byd 20 NM blo 7,000'

018°-037° byd 20 NM blo 10,000'

038°-051° byd 18 NM blo 5,000'

052°-074° byd 35 NM blo 10,000'

075°-116° byd 33 NM blo 4,000'

117°-142° byd 12 NM blo 10,000'

158°-170° byd 24 NM blo 10,000'

279°-301° byd 15 NM blo 10,000'


302°-342° byd 20 NM blo 10,000'

343°-359° byd 20 NM

DME unusable:

127°-173° byd 30 NM blo 3,000'

237°-302° byd 30 NM blo 4,000'



WHITFIELD FARMS (See HURDLE MILLS on page 325)

WILKES CO (See NORTH WILKESBORO on page 344)