

MARION

VAIDEN FLD (A08) 8 SW UTC-6(-5DT) N32°30.63' W87°23.09'

220 B NOTAM FILE ANB

RWY 16-34: H6400X80 (ASPH) S-30, D-50 MIRL

RWY 16: PAPI(P2L)—GA 3.0° TCH 40'. Tree.

RWY 34: PAPI(P2L)—GA 3.0° TCH 40'.

SERVICE: LGT All airfield lighting currently inoperable. Arpt bcn currently inoperable. Rwy 16-34 lgts lctd 10' from rwy edge.

AIRPORT REMARKS: Unattended. Rwy 16-34, 80' overlay, side transitions smooth. Rwy 16 and 34 markings svrly faded or obsc.

AIRPORT MANAGER: 734-250-4119

COMMUNICATIONS: CTAF 122.9

Ⓡ ATLANTA CENTER APP/DEP CON 132.25

CLEARANCE DELIVERY PHONE: For CD ctc Atlanta ARTCC at 770-210-7692.

RADIO AIDS TO NAVIGATION: NOTAM FILE ANB.

BROOKWOOD (L) (L) VORTACW 111.0 OKW Chan 47 N33°14.27' W87°14.99' 189° 44.1 NM to fld. 655/OE.

VOR unusable:

015°-035° byd 5 NM blo 4,900'

035°-070° byd 5 NM blo 3,400'

155°-165° byd 20 NM blo 4,900'

195°-205° byd 15 NM blo 9,900'

195°-205° byd 5 NM blo 4,900'


270°-320° byd 30 NM blo 4,900'

320°-015° byd 20 NM blo 4,900'

DME unusable:

344°-011° byd 34 NM

ATLANTA
H-6K, 9A, 12F, L-18H
IAP



MARION CO—RANKIN FITE (See HAMILTON on page 58)

MARK REYNOLDS/NORTH MOBILE CO (See CREOLA on page 45)

MARRA N32°18.70' W86°30.64' NOTAM FILE MGM.

NDB (MHW) 245 MG 097° 6.0 NM to Montgomery Rgnl (Dannelly Fld). 240/1W.

ATLANTA
L-181