

AJO

ERIC MARCUS MUNI (PØ1) 5 N UTC-7 N32°27.17' W112°51.68'

1450 B NOTAM FILE PRC

RWY 12-30: H3800X60 (ASPH) S-12 MIRL 0.6% up SE

SERVICE: LGT PAPI Rwy 12 and 30; MIRL Rwy 12-30 opr SS-SR and preset low intst; incr intst—CTAF.

AIRPORT REMARKS: Unattended. Rwy 12-30 asph and gravel stwy 1400 ft NW end; 1065 ft stwy SE end; asph broken and brush on stwys byd 200f t fm thr. 2 x 2 ft exposed conc cable mrks both sides of rwy wi 20 ft of paved sfc. Rwy 30 4 ft dike 1340 ft fm thr. 6-10 ft raised panels acrs ramp 70 ft in front of T-hngrs; mkd with paint. Mt all quads. Mil jet tfc and livestock on and infov arpt. NOTE: See Special Notices—Restricted Area R-2305, Gila Bend, Arizona Transit Information.

AIRPORT MANAGER: 520-627-3951

COMMUNICATIONS: CTAF 122.9

AJO RCO 122.2 (PRESCOTT RADIO)

RADIO AIDS TO NAVIGATION: NOTAM FILE PRC.

GILA BEND (VH) (H) VORTAC 116.6 GBN Chan 113 N32°57.38' W112°40.46' 183° 31.6 NM to fld. 790/14E.

TACAN AZIMUTH unusable:

360°-010° byd 25 NM

VOR unusable:

091°-101° byd 40 NM blo 18,000'

102°-114° byd 40 NM blo 6,500'

102°-114° byd 53 NM blo 15,000'

102°-114° byd 79 NM

115°-189° byd 40 NM

211°-213° byd 40 NM


287°-292° byd 40 NM

293°-303° byd 40 NM blo 18,000'

304°-331° byd 40 NM

352°-090° byd 40 NM

PHOENIX
L-5B



AK-CHIN RGNL (See MARICOPA on page 64)

AVI SUQUILLA (See PARKER on page 70)