

**GILA BEND MUNI** (E63) 2 E UTC-7 N32°57.61' W112°40.42'

789 B TPA-1589(800) NOTAM FILE PRC

PHOENIX  
H-4J, L-5B, A

**RWY 04-22:** H5200X75 (ASPH) S-12.5 MIRL 0.3% up NE

**RWY 04:** PAPI(P2L)—GA 3.0° TCH 40'. Tree.

**RWY 22:** PAPI(P2L)—GA 3.0° TCH 40'. Tree.

**SERVICE:** FUEL 100LL LGT ACTVT MIRL Rwy 04-22—CTAF. CTAF lgt  
OTS indefly. Windssock OTS indefly. Airport beacon OTS indefly. Intens  
Rwy Lights: Rwy 04-22 OTS indefly. Twy lgt OTS indefly.

**AIRPORT REMARKS:** Unattended. 100LL self svc H24 with credit card. Rwy  
04-22 primary sfc +5-20 ft brush and trees 100-125 ft S of cntrln.

Area alg rwy nrws to 30' at culvert. NOTE: See Special

Notices—Restricted Area R-2305, Gila Bend, Arizona Transit  
Information.

**AIRPORT MANAGER:** 623-810-4662

**COMMUNICATIONS:** CTAF/UNICOM 122.8

**RCO** 122.1R 116.6T (PRESCOTT RADIO)

**CLEARANCE DELIVERY PHONE:** For CD ctc Luke Apch at 623-856-7361. If una  
ctc Albuquerque ARTCC at 505-856-4861.

**RADIO AIDS TO NAVIGATION:** NOTAM FILE PRC.

**(VH) (H) VORTAC** 116.6 GBN Chan 113 N32°57.38'

W112°40.46' at fld. 790/14E.

TACAN AZIMUTH unusable:

360°-010° byd 25 NM

VOR unusable:

091°-101° byd 40 NM blo 18,000'

102°-114° byd 40 NM blo 6,500'

102°-114° byd 53 NM blo 15,000'

102°-114° byd 79 NM

115°-189° byd 40 NM

211°-213° byd 40 NM

287°-292° byd 40 NM

293°-303° byd 40 NM blo 18,000'

304°-331° byd 40 NM

352°-090° byd 40 NM

