

NUGGET BENCH (33AK) PVT 1 SE UTC-9(-8DT) N62°31.04' W150°56.72'**ANCHORAGE**


2010 NOTAM FILE

RWY 01-19: 1240X38 (GRVL)**RWY 01:** Brush.**RWY 19:** Brush.**AIRPORT REMARKS:** Unattended. Rwy 01-19 width varies 38 to 81'. 5' high brush 20' from approach end of Rwy 19.**AIRPORT MANAGER:** 907-279-1560**COMMUNICATIONS:** CTAF 123.65**RADIO AIDS TO NAVIGATION:** NOTAM FILE TKA.**TALKEETNA (H) (H) VORW/DME** 116.2 TKA Chan 109 N62°17.90' W150°06.32' 281° 26.9 NM to fld. 568/19E.**VOR unusable:**

277°-297° byd 30 NM blo 12,000'

DME unusable:

057°-087° byd 30 NM blo 13,000'

COMM/NAV/WEATHER REMARKS: For a toll free call to Kenai FSS dial 1-800-864-1737.**NUIQSUT****ALPINE AIRSTRIP** (AK15)(PALP) PVT 8 N UTC-9(-8DT) N70°20.66' W150°56.69'**POINT BARROW**

21 NOTAM FILE FDC Not insp.

H-1A, L-4J**RWY 04-22:** 5005X100 (GRVL) MIRL**RWY 04:** ODALS. PAPI(P4L)—GA 3.15° TCH 50'. Tower.**RWY 22:** ODALS. PAPI(P4L)—GA 3.16° TCH 50'.**SERVICE:** LGT ACTVT ODALS Rwy 04 and Rwy 22; MIRL Rwy 04 and Rwy 22—CTAF. PAPI Rwy 04 and Rwy 22 by req—907-670-4005.**AIRPORT REMARKS:** Arpt unattended. Status, cond and grd ops—907-670-4005. 24 hr PPR bfr Indg—907-670-4002. All arr rpt 10 mi final on CTAF. Rwy 04-22 40 x 80 ft runup pad 153 ft fm thr both ends. Rwy ops PPR; rwy used as aces road; psbl PAEW on rwy. Cold temperature airport. Altitude correction required at or below -33C.**AIRPORT MANAGER:** 907-263-3512**WEATHER DATA SOURCES:** SAWRS.**COMMUNICATIONS:** CTAF/UNICOM 122.8® **ANCHORAGE CENTER APP/DEP CON** 134.4**COMM/NAV/WEATHER REMARKS:** For a LC to Deadhorse FSS dial 659-2401. For a toll free call to Fairbanks FSS dial 1-866-248-6516. Lcl wx use AQT ASOS.