

LOC I-DQG 111.7	APP CRS 003°	Rwy Idg 10000 TDZE 707 Apt Elev 748	ILS RWY 36C (CAT II & III) CHARLOTTE/DOUGLAS INTL (CLT)
---------------------------	------------------------	--	---

RADAR required for procedure entry. DME or RADAR required.		ALSF-2	MISSED APPROACH: Climb to 3000 on CLT VOR/DME R-001 to TOMME/CLT 15.4 DME and hold.
Simultaneous approach authorized. DQG ILS ILZ Rwy 36C unusable for rollout guidance.			

D-ATIS ARR 121.15 DEP 132.1	CHARLOTTE APP CON (001°-119°) 128.32 (120°-295°) 120.05 (296°-360°) 134.75 (180°-359°) 257.2 (360°-179°) 307.8	CHARLOTTE TOWER (Rwys 18L-36R) 118.1 257.8 (Rwy 18C-36C) 126.4 257.8 (Rwy 18R-36L) 133.35 257.8	GND CON 121.8 348.6 (WEST) 121.9 348.6 (EAST)	CLNC DEL 127.15 348.6
---	--	---	---	---------------------------------

